MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T.28 NR 5 W ...

| DESCRIPTION OF CORNER 1/4 Corner between Sections 24 & 25 DESCRIPTION OF CORNER MONUMENT 1* Pipe with 4* Brass cap WITTNESSES TO CORNER 6* Jack Pine + 8 73 E - 54 Links 9* B. Cherry - S 12 * - 50 Links DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR | | Kalkaska COUNTY |
|--|----------------------------|--|
| WITTNESSES TO CORNER 6* Jack Pine - 8 73 E - 54 Links 9* B. Cherty - S 12 * - 50 Links DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR | DESCRIPTION OF CORNER | 1/4 Corner between Sections 24 & 25 |
| 98 B. Cherry - S 12 W - 50 Links DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR | DESCRIPTION OF CORNER I | MONUMENT 1" Pipe with 4" Brass cap |
| DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR | WITTNESSES TO CORNER | 6* Jack Pine - S 73 E - 54 Links |
| DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR | - | 9" B. Cherry - S 12 W - 50 Links |
| DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR | - | |
| | - | |
| | Presentation of the second | |
| | | HOW CORNER WAS LOCATED AND IDENTIFIED OR |
| RESTORED. | | |
| This corner had been previously located and perpetuated by Marcus Schaaf, Registered Land Surveyor, from original B.T.'s. | | |

SURVEYORS SEAL

Corner was placed and witnessed March 12, 1951.