MAR U 3 1998	:	*		
	KENT COUNTY F	EMONUMENTATION		
SECTION	LAND CORNER RECOR	RDATION CERTIFICATE Act 74, Mich. P.A. 1970	5	RE 97
For corners in			<b>a</b>	A GREET
KENT COUNTY Locate	ed In: Corner Code #		REG.	R KENT
(County)	- I		9/1/2	3 5 5 5
1. Public Land Survey	T 5N R 9W I-11			
7 1	TR TR	<del></del>	3/3	
_	<u>TR</u>			<u> </u>
2. Property Controlling S in Section S	T R		9762	
3. Miscellaneous S	TR		0,0%	
Property in Sec. S	TR		Register of Deeds St	amp & File Number
m Diek				
Lot No, Recorded Plat Private Claims		1	A B C D E F	3 H I J K L M
J. 1 114415 J. 114115			2 - 6 - 5 - 4 -	<del></del>
viul Dunitalo	Feh 5 97		3	
I, Kirk Breitels in a fee requirements of P.A. 74, Michigan P.A. of	1970, the comer points mentioned in li	nes 1 and 2 above were in	5	10 11 12
conformance with regulations and rules there	efore as required in the current manual ( reall of I and Management or by a decre	of survey instructions of the see of a Court of Law and /or	6 18 17 16	15 14 13
that the corner points mentioned in lines 3, Board of Land Surveyors or by a Decree	4 and 5 above were in conformance will	in the rules of the Michigan .	7	
recovered, found as expressed below:	Of B Court of Early Spinsholder, 10		8 19 20 21	22-23-24-
NOTE: Not more than 2 corners, all in	the same town and range, may be r	ecorded	9	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
on this certificate.			10 30 29 28	20 20
			11 32 33 33 -	34 35 36
			13	
A. Description of original monument	and accessories and/or subsequer			•
I-11 1830 GLO	Mullett	Set Post Monument		
1946 Kent Co. 1974 LCRC #746		3/4" Iron		•
1981 LCRC #224	l8 Jonker	Set Kent County Kent County Monu		
1994 LCRC #701		·		
The position of this c Peer Group, monumented	orner was previously a I by Robert J. Jonker (	pproved by the Ken on 11/6/81 and was	t County Remonur recorded per LC	nentation CRC #2248
B. Description of corner evidence fo	und and/or method applied in rest	oring or reestablishing come	r.	a act by
r as Found standard Ve	ent Co. Mon. (Harrison lace of the 3/4" Iron	ስ per witnesses ፣፣	rom above Luku a	Iron and
Conc. Monument check v	with Kent Co. Wit. and	LURU #/40.		
LCRC #2248	<u>L</u> (	<u>CRC #2248</u> Nail & tag cor. fc	. post SOO°W :	33.48'
Remon. tag cor. fc. p Remon. tag 36" Oak	N73°W 134.18'	Nail & tag 40" Oak	N73°W 1	34.08'
Remon. tag 8"-10" B'v	wood S74°W 61.40'	Nail & tag 12"-15" "X" on E. end culv	B'wood S74°W ( ert N22°E (	31.30° 48.76'
"X" on E. end culver "X" on W. end culver	L NOTON 40 04'	"X" on W end culy	vert N21°W	50.05'
وستقط والتابات وسيرا	is accounted by ma a	und is generally a	accepted by pro	fessional ner
surveyors as the best C. Description of monument for corn	available evidence of	The position of t	HE OLIGINAL COL	
T-11 Standard Kent Co	untv Monument	:	33.48'	
Nail & KC Remon	. tag W. side cor. fen . tag S. side 40" Oak	ce post S00°W N73°W	134.08'	
Nail & KC Remon	. tag N. side 12" & 15	" Basswood S74°W	61.30'	KIRK
"X" cut on E. e	nd conc. culvert	N22°E N21°W	48.76' \$ 50.05'	BESTELS TO
"X" cut on W. e On approx. C/L	nd conc. culvert "X" road			SURVEYOR A
			A 21	ACCOUNT OF S

Signed by Surveyor's Michigan License No.

30077

P.A. 345 1990 KENT COUNTY PEER APPROYED/3/27/97

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995