## SURVEY & REMONUMENTATION

MAR 0 3 1998

## KENT COUNTY REMONUMENTATION

LAND	CORNER	RECOR	DATIC	N CE	RTIF	ICATE
Filing	ı Requiren	nent of Ad	rt 74	Mich	DΔ	1970

For corners in SECTION		1 9 20
KENT COUNTY Located In:	Corner Code #	REG. REG.
(County)		3.0 k   82 min
1. Public Land Survey T_5! TT_T_	N R 9W J-11 R R	PETERS PROPERTY OF THE PETERS
2. Property Controlling S T in Section S T 3. Miscellaneous S T	R R	9768
Property in Sec. S T		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		
5. Private Claims		A B C D E F G H I J K L
		2 6 5 4 3 2 - 1
Kirk Breitels in a field survey	y on, 19, 19 do hereby state th	
requirements of P.A. 74, Michigan P.A. of 1970, the conformance with regulations and rules therefore as re-	corner points mentioned in lines 1 and 2 above	ve were in
United States Department of the Interior, Bureau of La that the corner points mentioned in lines 3, 4 and 5 a		
Board of Land Surveyors or by a Decree of a Corecovered, found as expressed below:	urt of Law; established, re-established, monu	numented, 8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same	town and range, may be recorded	9
on this certificate.		10 - 30 - 29 - 28 - 27 - 26 - 25
		11 32 33 35 36
		13
A. Description of original monument and acce	ssories and/or subsequent restoration;	
J-11 1830 GLO 1946 Kent Co. Wit.	Mullett Set Post Monument	
1946 Kent Co. Wit. 1974 LCRC #746	Bonnema 1 1/2" I	Iron
1981 LCRC #2251 1994 LCRC #6984		ut County Monument ounty Monument
The position of this corner Peer Group, monumented by R	was previously approved by obert J. Jonker on 11/6/81	y the Kent County Remonumentation and was recorded per LCRC #2251
Robert J. Jonker in place o with Kent Co. Wit. and LCRC LCRC #2251 Remon. tag 10" Cherry Remon. tag Tri. 6" Cherry Remon. tag fence post	o. Mon. (Harrison) per with f the 1 1/2" x 30" Crimped #746.  LCRC #6984 S53°W 48.42' Spike in 40 S53°W 35.64' Face steel N04°E 32.81' Nail & tag S64°E 63.80' Nail & tag	nesses from above LCRC as set by Iron he found. Said Iron checks  40" Oak S64°E 63.76' I fc. post N61°E 59.75' G 6" Cherry S30°W 35.60'
The selected location is a surveyors as the best avail C. Description of monument for corner and ac	accepted by me and is gene	nerally accepted by professional
J-11 Standard Kent County M Spike in NE side 40" Face of steel fence p Nail & KC Remon. tag Nail & KC Remon. tag SE cor. 6" x 9" wood C/L E-W asph. rd. is	onument Oak S6 ost N6 NW side 8" Cherry clump S3 E. side P. Pole S2 mail box post N6	664°E 63.76' 161°E 59.75' 530°W 35.60' 520°W 44.79' 105°W 18.21' SURVEYOR 30077
Signed by Knk But	2	
		ate 3/27/97
Surveyor's Michigan License No. 30077		

P.A. 345 1990 KENT COUNTY
PEER APPROVED 3/27/97
CHAIRMAN Forum Huberr