## SURVEY & **REMONUMENTATION**

APR 27 1995

Kent County Remonumentation

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

STATE OF MICHIGAN COUNTY OF KENT REČĚÍVED FÖR RECORD

94 DEC 30 PM 12: 06

1 01 00111010 111																
F	(County)	<del></del>		edin: wne Twp	• :	Corner Code ##			RE(	3. OF	DE	ΈŌ	)\$			
1.	Public Land Survey		т <u>5</u>	N R 9W		L-10			•	- : 1						
			T T	R R	<sub> </sub> .				:		÷ Y		,			
			Ť_	R					•	:	:					
2.	Property Controlling	S	T_	R		and the contract of			/ last	in r	Ч Л		•			
	in Section	s	T _	R	_	The second secon			. 8	97	1 4					
3.	Miscellaneous	S	T	R	<u>.</u>		Regist	er of C	)eeds	: Sta	mn	۶ F	امات	Mun	aher	
	Property in Sec.	S	T	R	<del>-</del> :	The second second	1,09.0.					<u>.                                    </u>				· `.
4.	Lot No,	Recorded	d Plat					A D	С Г	; }	: - c	G	н		K	1.33
5.	Private Claims				4 **.	profit the Committee of		î	ŤŤ		<del></del>	<del>–</del>	<del></del>		<del></del>	<del></del> -

Robert Jonker, in a field survey on. <u>December</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Not set in GLO survey

1944, Old Kent Co. wit. map - 1" Iron

1974, LCRC #636, D. Bonnema, PS#12679, Found iron in mon.box & checks with prev. witnesses

Took new witnesses:

SE corner house fnd. NW 116.82'

NNW 141.18' Jonker, 1992, Found boat spike in PK-side P.pole mon. box

41.04 PK-side P.pole Ε

Fence corner post SW corner fr. shed W 28.25 40.85 NE

C/L B.T. West 1.0'B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found boat spike in mon. box, raised over 1" iron by wit. per LCRC #636 Calculated intersection of 4 lines is 8.7 ± South & 2.1 ± East

P.A. 345 1990 KENT COUNTY PEER APPROVED /12 //5/

CHAIRMAN /

This position not established by original government surveyors, monument is accepted as the best available evidence of teh position of the corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced with 4" standard K.C. Harrison monument in mon. box.

21572

K.C. N&T N. side P. pole N 85° E 41.08'
K.C. N&T N. side 18" Boxelder N 90° W 49.42'

NE cor. 24" Pine N 20° W 100.51' K.C. N&T

N 55° W 116.83' SE corner house fnd.

C/L N-S road is 1' West

on line with fence to West

TO THE PARTY OF TH JONKED LAND SU

The way in the commence of the comment of the comme

LAND SURV

Surveyor's Michigan License No.

Date

December 28, 1994