IRVEY & REMONUMENTATION

1	
1/	
1/1/	
////	

MAR 0 3 1998

KENT COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTI	ON Filli	Filing Requirement of Act 7		
(County)	Located in:	Corner Code #		
Public Land Survey	T <u>5N</u> R TR TR	9W M-12	_ _ _	
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR			




Register of Deeds Stamp & File Number

4. Lot No,	Recorded Plat	:
Private Claims _		_

, 19 97 do hereby state that under Mar. 13 ຼ, in a field survey on _ˈ requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate



A. Description of original monument and accessories and/or subsequent restoration:

M-12	1830	GLO	Mullett	Set Post
	1961	Kent Co. Wit.		"X" on stone
	1978	LCRC #1131	VanKooten	RR Spike
	1981	LCRC #2158	Jonker	Set Kent County Monument
	1994	LCRC #7001	Byl	Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 9/17/81 and was recorded per LCRC #2158

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-12 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Robert J. Jonker in place of the RR Spike he found. Said RR Spike checks with Kent Co. Wit. and LCTRC #1131.

LCRC #2158		<u>LCRC #7001</u>
Remon. tag 8" Elm	N62°W 44.5	9' Nail & tag 15" Elm N62°W 44.91'
Remon. tag 16" Cherry	S72°W 78.9	O' Nail & tag 24" Cherry S72°W 79.00'
Remon. tag 8" Ash	N29°W 76.0	2' Nail & tag 15" Elm N25°W 69.15'
Remon. tag Fe. post	N53°E 37.7	3' Nail & tag 8" Elm N35°E 40.82'
		Nail & tag 8" Flm N70°F 32.76'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

. Descrip	tion of monument for corner and accessories established to perj	petuate locating the position of the	e corner:
M-12	Standard Kent County Monument	•	25 May 1 May
	Nail & KC Remon. tag S. side 15" Elm	N62°W 44.97'	95 2/69
	Nail & KC Remon. tag S. side 26" Cherry	S72°W 78.96'	
	Nail & KC Remon. tag E. side 18" Elm	N25°W 69.15'	KIRK N
	Nail & KC Remon. tag W. side 10" Elm	N35°E 40.82'	BESTELS T
	Nail & KC Remon. tag NE side clump 4" Ti	ees S60°E 31.94'	E AMD
	Fence to West is 9'± North	*	SURVEYOR
	Fence to East is 24'+ North		30077
	C/L North-South gravel road is East 4'±		
ianed by	Kuh Pruts	Date 3/27/97	The state of the s

30077 Surveyor's Michigan License No._

P.A. 345 1990 KENT COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, A REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995