

## BUTWEY & HEMONUMENTATION

	う. FEB 1	A 3007					
6	<b>2\</b> *		<b></b>				,
Ford	COMA		ER RECORDATION CE rement of Act 74, Mich OUNTY REMONUMENT.	i. P.A. 1970		96 96	0 0 0 0
	Kent	Located in: Caledonia	Corner Code #	1	哥一		
	(County)	Township			₽ } \	1 6	alimoni Zijo
1.	Public Land Survey	T R T R	F-10		OF DEEDS	8 HH 9:	102 KENT
2.	Property Controlling s	T R		ļ		ਯ ਵ	5
i	in Section s	T R			9426		•
	Miscellaneous s	T R		Ren	ister of Deeds Stan	nn & File N	lumber
	Property in Sec. s	T R					
4. I	Lot No, Reco Private Claims	rded Plat			A B C D E	FGH	
V. I	i iivate Olaiiiis				Î		
					2 6 5	4	
		,			3	+-	<del> </del>
do he in ling curres Mana above Court	Randy Kolehouse, pereby certify that under requirences 1 and 2 above were in continuous manual of survey instruction agement or by a decree of a Coute were in conformance with the cof Law; established, re-estated below:	nents of P.A. 74 Michigan P.A nformance with regulations a ns of the United States Depa art of Law and/or that the com	A. of 1970, the corner point and rules therefore as req artment of the interior, Bur her points mentioned in line of Land Surveyors or by a	ts mentioned quired in the reau of Land as 3, 4 and 5 Decree of a	4 7 3 5 6 18 17 7 7 8 19 20 9	9 10 10 11 15 12 12 12 12 12 12 12 12 12 12 12 12 12	11 12 13 13 13 13 13 13 13 13 13 13 13 13 13
NOTE		rs, all in the same town an	d range, may be record	ed	10 30 29	27	2525
	on this certificate.	•			11		
A.	Description of original mo	nument and accessories	and/or subsequent rest	oration:	12 31 32	33 34	35 36
F-10	This corner was not origina	dly set by the G.L.O.					
	N/A Witness Map	K.C. Surveyor	lron				
	1973 L.C.R.C. #618	F. Spicer	1" Iron	P.A. 34 PEER / CHAIRN	45 1990 KENT ( APPROVED EL MANTALLA	COUNTY	16
					/	·	
₿.	Description of corner evid	ence found and/or methor	d applied in restoring or	r reestablishing	g corner:		
F-10	Found 1/2" iron per L.C.R.C	C. #618. Iron is 0.4' West a	and 0.2' South of the inte	ersection of 1/4	lines. Accepted in	on as Cen	ter
	of Section.	!			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		• • • • • • • • • • • • • • • • • • • •
			;				
	L.C.R.C. #618 6" Crabapple S 07° E 36.35	· · · · · · · · · · · · · · · · · · ·					
	6" Poplar S 80° E 48.55' 24" Elm N 80° W 38.89'						
	21 23111100 11 00.00						
	The selected location is according the position of the original		ully accepted by profession	onal surveyors a	as the best availab	le evidenc	e
<b>c</b> .	Description of monument	for corner and accessorie	s established to perpet	uate locating th	he position of the	corner:	
<del>-</del> -10	Replaced 1/2" Iron with a Si	A Company of the Comp		•	10202 20 E	Michael	·c.
, ,	TISPICOG IZ HOR MILI CO	E COUNTY WORK	inon.		12 2 4 6 2 0 2 0 2 0 2 0 2 0 2 0 2 0 2 0 2 0 2	, M/G	4
		g on N side 10" Elm N 80° E				YDY I.	7
	Nail & K.C. remon. tag	g on N side 10" Ash S 79° E g on SW side 12" Ash S 35° g on W side Multiple 8" Elm	° E 54.58'		SUR	EHOUSE LAND RVEYOR No.	***************************************

Nail & K.C. remon. tag on N side Multiple 6" Box Elder N 86° W 45.71'

25854

Muchy Koh

Surveyor's Michigan License No. \_\_\_\_\_

Signed by\_

25854 25854 LAND SURVENIENT