

FEB 1 4 1997

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

For corners in Kent				TY REMONUMENTA	ATION \ \ \frac{\sigma}{\sigma} \ \frac{\sigma}{\sigma} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
			Located in: Caledonia	Corner Code #	REG. C. TO CESONE
		unty)	Township	0011101 0000 #	
1.	Public Land	d Survey	T R	H-8	FOR NECO
			T R		22 PB
2.	Property C		T R		i i
	in Section	s	T R		9515
	Miscellane	· · · ·	•		Register of Deeds Stamp & File Number
	Property in	Sec. s	T R		Tregister of beeds stamp & the Hamber
4.	l at Na	Popord	ad Diat		
4. 5.	Privata Cla	ime , necorde	ed Plat		A B C D E F G H I J K L
Э.	Filvate Cla	11115			
					2 - 6 5 4 3 2 1
					3
1.	Randy Kol	ehouse in:	a field survey on March 2	26 19	96 4 7 8 9 10 11 11 11 11 11 11 11 11 11 11 11 11
I. <u>Randy Kolehouse</u> , in a field survey on <u>March 26</u> 19 do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the comer points m					mentioned s
in lines 1 and 2 above were in confort			mance with regulations and re	ules therefore as requ	aired in the
			of the United States Departmen		au of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a					
			es of the Michigan Board of Laf blished, monumented, re-mor		
	ssed below:		bilistica, monamentea, re-mor	iumenteu, recovereu,	lound as
NOTI			all in the same town and rar	nga may ha tacatda	10 30 29 28 27 25 25
		s certificate.	an in the same town and rai	ige, may be recorded	"
	On (III	5 John Marie			12 31 32 33 34 35 36
A.	Descripti	on of original monu	ment and accessories and/o	or subsequent restor	ration: 13
H-8	This corner was not originally set by the G.L.O.				
	1956	Notes	Williams & Works	Set ⊦ron	
	1956	Witness Map	K.C. Surveyor	1" Iron	* · · · · · · · · · · · · · · · · · · ·
	1984	L.C.R.C. #3844	Exxel Engineering	"T" Iron	P.A. 345 1990 KENT COUNTY
		**.	EAAO: Eligiloofing	1 11011	PEER APPROVED <u>0/22/96</u>
					CHAIRMAN Janu Kuhen
					·
В.	Descripti	on of corner eviden	ce found and/or method app	olied in restoring or	reestablishing corner:
H-8	Found a "	T" iron 2.5' West of	the C/L of Alaska Avenue (bi	t ) running North and	South on line of a brush row and fence line
	Found a "T" iron 2.5' West of the C/L of Alaska Avenue (bit.) running North and South on line of a brush row and fence line running East per L.C.R.C. #3844, Williams & Works' notes (1956) and the K.C. Surveyor's records. "T" iron is 0.3' East of				
			ccepted iron as the Center of		2. Outvoyor o records. The foll is 0.0 East of
		L.C.R.C. #384	4		
	Spike in SW sde 18" Walnut NW 91.20' (m. 91.19')				
	Spike in S sde P. Pole fence post N 80° E 35.71'				
	PK in SW sde P. Pole S 35° W 76.09' (m. 76.06')				•
	C/L blacktop 2.5' East				
	1/2" iron 3.5' North and 7' East				
	HOILE	Hormand Las	•		
	The selec	ted location is accep	ted by me and is generally ac	cepted by profession	nal surveyors as the best available evidence
	of the pos	ition of the original c	orner.		:

·C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-8 Replaced "T" Iron with a Standard Kent County Monument

Nail & K.C. remon. tag on SW side 18" Walnut N 50° W 91.19'

Nail & K.C. remon. tag on S side fence post N 80° E 35.71'

Nail & K.C. remon. tag on SW side P. pole S 35° W 76.06'

Nail & K.C. remon. tag on N side 10" Quad Crabapple S 80° E 51.54'

1/2" iron 3.5' North and 7' East

Signed by\_ 25854 Surveyor's Michigan License No.

RANDY J. KOLEHOUSE LAND SURVEYOR CO LAND SU 25854

IVEYORS, JAN. 28, 1973 REVISED MAY 14, 195 REVISED JAN., 1% FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS,