SURVEY &

FEB 1 4 1997

Signed by 🔏

Surveyor's Michigan License No.

EARTH TECH

COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 KENT COUNTY REMONUMENTATION for corners in Corner Code # Located in: Gaines Kent (County) **Public Land Survey** R 11W **Property Controlling** in Section Miscellaneous Register of Deeds Stamp & File Number Property in Sec. , Recorded Plat Private Claims in a field survey on January 22 Randy Kolehouse do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: P.A. 345 1990 KENT COU PEER APPROVED 31 Mullett Set Post 1831 G.L.O. Notes K.C. Surveyor iron & Stone 1963 Witness Map CHAIRMAN L.C.R.C. #683 "Bolt" Spike 1974 Exxel Engineering L.C.R.C. #2929 Fnd. "Bolt" Spike in a 3" x 30" Pipe / Set K.C. Monument **Exxel Engineering** 1982 K.C. Monument L.C.R.C. #5019 J. Bueche 1989 This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Exxel Engineering on 5/3/982 and was recorded per L.C.R.C. #2929. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found a Standard Kent County Monument 0.5' West of the C/L of Eastern Avenue (bit.) running N-S on line of a fence running West per L.C.R.C.'s #2929 and #5019 as set by Exxel Engineering in place of a boat spike in a 3" x 30" iron they found which checked L.C.R.C. #683. L.C.R.C. #5019 L.C.R.C. #683 L.C.R.C. #2929 Nail & KC tag in S sde P. Pole West 108.00' Nail & Remon tag in S side p. pole West 108.00' Nail in sde P. Pole E 128.13' Nail in sde Fe Post W 50.53' Nail & KC tag in E sde MBT pole N 5° W 248.63' Nail & Remon Tag in E side MBT pole N 5° W 248.63' C/L Pvt. East 0.5' Nail & KC tag in S sde P. Pole East 128.24' Nail & Remon Tag in S side p. pole East 128.24' C/L blacktop West, East 0.5' C/L blacktop pavement East 0.5' The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Standard Kent County Monument Nail & K.C. remon, tag on E side P. pole N 05° W 248.63' RANDY J. Nail & K.C. remon. tag on S side P. Pole East 182.24' KOLEHOUSE Nail & K.C. remon. tag on W side 12" Elm S 40° W 110.65' LAND Nail & K.C. remon. tag on S side P. pole West 108.00' Nail & K.C. remon. tag on N side 12 Maple N 60° W 76.36'