

FEB 1 4 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

	For corners in			t of Act 74, Mich. P.A REMONUMENTATIO		١	9 20 0		
	Kent (County)	Locate		orner Code #		REG. C	AUG -		
The second secon	Public Land Surv	т	R	E-13		OF DEEDS	FOR RECO		
Control of the second second	Property Controll in Section Miscellaneous	ing S T S T S T			Regi	9253	es Constant S		
A CONTRACTOR	Property in Sec.	Property in Sec. STR					inp & The Number		
	Lot No. Private Claims	, Recorded Plat		авс р Е	FGHIJKI	L			
						2 6 5	4 3 - 2		
1000						3		-	
	I. Randy Kolehouse, in a field survey on January 19 19 96, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned					5	9	2	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land						6 18 17	15 14 1	 3 	
Management or by a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a						8 19 20	21 22 23 2	24—	
Ś		olished, re-established, ı				9		<u> </u>	
	NOTE: Not more th	nan 4 corners, all in the	same town and rang	e, may be recorded		10 30 29	28 27 26 2	5— 	
The second of the	on this cert	ificate.				12 31 32	33 34 35 3	36—	
	A. Description of	Description of original monument and accessories and/or subsequent restoration:				P.A. 345 1000	1	<u></u>	
	E-13 1817	G.L.O. Notes	L. Lyon	P.A. 345 1990 KENT COUNTY Set Post Stone PER APPROVED 3/2/96					
))	1941 1983	Witness Map L.C.R.C. #3391	K.C. Surveyor William Byl	Stone Fnd. Stone / S	et K.C. Mo	CHARMAN	amille		
	1989	L.C.R.C. #5043	nt	•	Tru	12			
	1	Note: This corner is not common with E-1, T4N, R11W.							
		This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by William Byl on 4/20/83 and was recorded per L.C.R.C. #3391.							
	H.,	Description of corner evidence found and/or method applied in restoring or reestablishing corner:							
200	(gravel) running	13 Found a Standard Kent County Monument 7' North of C/L of 108th Street (gravel) running East and 95' East of 8th Street (gravel) running South at old fence line to North per L.C.R.C.'s #3391 and #5043 as set by William Byl in place of a stone they found which checked Williams & Works records and K.C. Surveyor's records.							
	\	L.C.R.C. #3391	·		R.C. #5049	3			
	Nail & tag, S sd Nail & tag W sd Nail & tag W sd	Nail & tag, E sd. 12" Walnut N 05° W 56.95' Nail & tag, S sd. 16" Oak S 65° E 88.72' Nail & tag W sd. 12" Oak S 10° E 53.83' Nail & tag W sd. 8" Twin Oak S 40° W 58.35' NE corner Sec. 5, 4-11, (3/4" re-rod) West 101.20' Nail & Remon Tag W side 14" O Nail & Remon Tag W side 14" O Nail & Remon Tag W side 14" O					38.67') 53.70')		
		Nail & Remon Tag N side 12" Maple N 70° W 37.43' (m. 37.28') NE corner Sec 5, (3/4" re-rod) West 101.20' (m. 101.17') C/L gravel rd E-W, South 7' \pm , on old fence North							
San Artificial		The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.							
4.00	į ·	Description of monument for corner and accessories established to perpetuate locating the position of the corner:							
47.	E-13 Standard Kent County Monument								
A management		Nail & K.C. remon. tag on S side 18" Oak S 65° E 88.67 Nail & K.C. remon. tag on W side 14" Oak S 10° E 53.70'							
	Nail & K.C. remon. tag on W side 12" Oak S 40 W 58.29' Nail & K.C. remon. tag on N side 12" Maple N 70° W 37.28' RANDY J. ** **RANDY J. ** **KOLEHOUSE								
S. 15 . W. B.	New Nail 8	& K.C. remon, tag on Es emon, Capped Rebar Ni	side 16" Walnut 7' higl	n N 05° W 56.71'		*	LAND SURVEYOR No.		
Total Control	Signed by Man	dy I Kob	boun	Date	123/9	To the	25854		
	77	EARTH TECH					CAND SURFICE	_	
1	Surveyor's Michigan License No. 25854								