

JAN 2 3 1996

Surveyor's Michigan License No. 25854

& YEVAUS

MOTENTALINE

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			KENT COUNTY REMONUMENTATION									1	S 6	n n	e e
Kent (County)		Lo	cated in:		Corner C	ode #			÷	7) Tr 4				~4 }æ ~-}	
	(00	ounty)											\sim		हर्ग ->,
1.	Public Lan	d Survev	7	<u>5N</u> R	11W	F-4	<u> </u>			2	۾ _آ ر ۾		α -		T-1
••		,		R						r,	$\exists \mathscr{A}$	1		27 The	-
	•		7	R						1	3/4	~	₩.		5
_									÷	•	က ဂ (၁ ဂ)		N		. 3m
	Property C in Section	controlling									05	11		C)	
	ın section Miscellane	ous													
	Property in							F	Registe	r of D	eeds S	itamp &	& File N	lumbe	r
								<u> </u>							
4.	Lot No	, R	ecorded Pla	at					_						
5.	Private Cla	aims							- Å	. в	СВ	E F	G H	1 J	K L M
				,					2	— <u></u>	 5		 	<u> </u>	4-1-1
									3 -						
Ι,	Randy Ko	lehouse	, in a field	survey on_	Ma	ay 15	19	95 ,	4		8 	├ -�-	10	 	-12-
		fy that under i							5	-		 			+
		es 1 and 2 abov anual of survey							6	—18—	17-	16	15-	14-	13-1.
Land	Manageme	ent or by a decre	ee of a Cour	t of Law and	d/or that t	the corner poin	its mentioned in	lines 3,	7						
4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or becree of a Court of Law; established, re-established, monumented, re-monumented, recover							8 -	19 I		21	22	23-	24		
		sed below:	stabilished, i	e-establishe	eu, mont	imented, re-m	onumented, rec	covered,	9			 -			
NOT	• .	nore than 4 co	rners, all in	the same	town ar	nd range, ma	y be recorded		10	3'0	29—	28—	27	26-	25-
		is certificate.	·						11					1	+ + -
										—31— 	32	33-	34	35 —	36
A.	Descript	ion of original	monument	and acces	sories	and/or subsec	quent restorat	ion:	13 L		<u> </u>	<u>l</u>	<u></u>	11	
F-4	This corner was not originally set by the G.L.O.														
	1922	1922 Survey Records Williams & Works Iron & Stone													
	1972			Medema, Van Kooten & Assoc.				Set Iron at Inter			/4 Line	es			
	1977	Survey Reco	ords	Exxel Engir	neering		1" Iror	ו		4- 46	00.10		201181	TV	
								۲	'.A. 34	45 18	90 K	= 14	COUN	10	6
					•			F	PEER	APP	ROVE	D; <u>ZO</u>	[26 40)	17	-/
								C	HAIR	MAŊ	77	<u> </u>	2/1/	pec	nec
В.	Descript	ion of corner e	vidence fo	und and/or	method	d applied in re	estoring or ree	establish	ing co	rner:			,		
F-4	Found a 1" iron per L.C.R.C. #166 as set by Medema, Van Kooten & Assoc. near corner of fence running North & East. This iron is within 0.10' of the intersection of 1/4 lines. Checked the following measurements from Williams & Works 1922 survey.														
		Center to E 1/4				1922 = 2,657. 1922 = 2,656.:									
	Accepted	d iron as Cente	r Section.												
		L.C.R.C. #166	5				•								
	Nail in si	de of fe post Si de of fe post N de of P. pole N	9.70'								•				
C.	Descript	ion of monume	ent for corn	er and acc	essorie	s established	to perpetuate	locating	the p	ositio	n of th	ie corn	er:	10	
F-4	Replace	1" iron with Sta	ındard 4" x	30" Kent Co	ounty Mo	onument,						y a TE	OF A	NCH	
	Na	il & K.C. remon	tag in W o	ide of fence	noet Su	01° E 2 10'					22.2	6	RANDY	٠, ٠	12.
		il & K.C. remon									2	ا	KOLEHO		9
		il & K.C. remon	_		•			•			<u> </u>		LAN SURVE		*
		il & K.C. remon	_								1	c .	No.	5.4	
		_									*	$c_{c_{\mathcal{V}}}$.	4000		GOLLI.
			_	. /	. /				,			44 O.C.	LAND	SURY	11911