SURVEY & REMONUMENTATION

FEB 1 4 1997 LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 KENT COUNTY REMONUMENTATION For corners in Located in: Gaines Corner Code # Kent (County) Public Land Survey T 5N R 11W **Property Controlling** 9277 in Section Miscellaneous Register of Deeds Stamp & File Number Property in Sec. , Recorded Plat_ Private Claims Randy Kolehouse in a field survey on January 2 do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: P.A. 345 1990 KENT COUNTY H-3 1831 G.L.O. Notes Mullett Set Post 1961 Witness Map K.C. Surveyor 1" Iron PEER APPROVED \$ 17/86 1/2" Iron in Mon. Box 1976 L.C.R.C. #931 Exxel Engineering 1981 L.C.R.C. #2828 Jonker Land Survey Fnd. 1/2" Iron in Mon. Box 1989 L.C.R.C. #5062 K.C. Monument J. Bueche 1994 L.C.R.C. #7157 Giaza K.C. Monument This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Rob Jonker on 4/1/82 and was recorded per L.C.R.C. #2828. В. Description of corner evidence found and/or method applied in restoring or reestablishing corner: H-3 Found a Standard Kent County Monument in the C/L of 68th Street (bit.) running E & W per L.C.R.C.'s #2828, #5062 and #7157 as set by Rob Jonker in place of a 1/2" iron in a monument box he found that checked L.C.R.C. #931 and K.C. Surveyor's records. L.C.R.C. #5062 L.C.R.C. #7157 L.C.R.C. #2828 Remon. tag on E side p. pole S 12° w 52.6' Nail & Remon Tag on E side p. pole S 12° W 52.6' Nail & K.C. remon tag in E side P. pole S 12° W 52.60' Remon, tag on SW side p. pole N 52° W 103.83' Nail & Remon Tag on SW side p. pole N 52° W 103.83' Nail & K.C. remon tag inSW side P. pole N 52° W 103.83' Nail & K.C. remon tag in E side T. pole N 00° W 39.15' Remon. tag on W side t. pole N 00° W 39,26' Nail & Remon tag on W side t. pole N 00° W 103.03' (m. 39.15') (m. 35,15') C/L MH, East along C/L 148.37 SW corner of concrete patio N 30° W 87.63' SW cor. conc. patio N 30° W 87.63' SE cor. conc. patio N 35° E 85.60' SE corner of concrete patio N 35° E 85.60' On C/L East-West pavement The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Standard Kent County Monument

Date

Nail & K.C. remon, tag on E side P. pole S 12° W 52.60' Nail & K.C. remon, tag on SW side P. pole N 52° W 103.83'

Nail & K.C. remon. tag on E side T, pole N 00° W 39.15'

ZÁRZH TECH

25854

SE cor. conc. patio N 35° E 85.60' SW cor. conc) patio N 30° W 87.63'

Signed by

Surveyor's Michigan License No.

randy J. Kolehouse

LAND