## SUFFVEY &

FEB 1 4 1997

## LAND CORNER RECORDATION CERTIFICATE

For corners in COMMISSION			Filing Requirement of Act 74, Mich. P.A. 1970 KENT COUNTY REMONUMENTATION				S R	
	Kent (Cou	Loc nty)	ated in: Gaines Township	Corner Code #		REG. OF	26 - 98 - 98 - 98 - 98 - 98 - 98 - 98 - 9	
1.	Public Land	T_ T_	R	H-7		FDEEDS	64 8 47 COSO COSO COSO COSO COSO COSO COSO COS	
	Property Co in Section Miscellaneo	ntrolling S T_ S T_	R			9279		
	Property in S		R		R	egister of Deeds Stamp	& File Number	
4.	Lot No	, Recorded Plat	<del> </del>		·			
I, do he in lin curre Mana abov Cour	Randy Kole ereby certify t les 1 and 2 a ont manual of agement or by e were in con t of Law; essed below: E: Not mo on this	house , in a field shat under requirements of Pabove were in conformance survey instructions of the Law adecree of a Court of Law aformance with the rules of the established, re-established ore than 4 corners, all in the certificate.  In of original monument and G.L.O. Notes Witness Map L.C.R.C. #34 L.C.R.C. #263 L.C.R.C. #1802 L.C.R.C. #5064	Janus A. 74 Michigan P.A. o with regulations and Inited States Departn and/or that the comer e Michigan Board of I monumented, re-m he same town and i	ary 2  of 1970, the comer point rules therefore as repent of the interior, But points mentioned in limit and Surveyors or by anonumented, recovered arange, may be recorded for subsequent reserved.  Sometimes of the subsequent reserved arange for subsequent reserved arange.	nts mentioned equired in the ureau of Land nes 3, 4 and 5 a Decree of a ed, found as ded  Storation:  Set Post T' Iron T' Iron Ton in Mon. Bot	n. Box / Set K.C. Monun	3/7/96	
	1994 This corne	L.C.R.C. #7171  er was originally approved and was recorded per L.C.R.	Glaza Assoc. by the Kent County	K	.C. Monument		liam Byl on	
3.	Descriptio	n of corner evidence fou	nd and/or method a	applied in restoring o	or reestablishi	ing corner:		
<del>1-</del> 7	and #7171	tandard Kent County Mon as set by William Byl in cked the same location of '	place of an iron in	a monument box he	found that ch			
	L.C	C.R.C. #1802	L	C.R.C. #5064		L.C.R.C. #7171		
Nail & tag, N side MBT pole S 50 W 49.00' Nail & tag, N side Transformer pole N 05 W 47.24' Nail & tag, W side 10" Elm S 30 E 57.06' NE Corner foundation Hse #2806 (at ground level) S 40 E 57.06' (m. 145.28)			Nail & Remon Tag N side MBT pole S 50° Nail & Remon Tag W side Transformer po' N 05° W 47.24' New Nail & Remon Tag W side 18" Willow S 30° E 57.03' NE comer foundation Hse #2806 (at groun S 40° E 145.25' (m. 145.28)		49.00' Nail & K.0 N 05° Nail & K.0 Noil & K.0 NE come	49.00' Nail & K.C. Remon tag in W side transformer pole N 05° W 47.24' Nail & K.C. remon tag in W side 24" Willow S 30° E		
	The selected location is accepted by me and is generally accepted by professional surve of the position of the original corner.					•	vidence	
<b>)</b> .	Descriptio	Description of monument for corner and accessories established to perpetuate locating the position of the corner:						
l-7	Standard Kent County Monument				_	-4864984	istera i ference	
	Nail 8 Nail 8	& K.C. remon, tag on NW s & K.C. remon, tag on W sid & K.C. remon, tag on W sid or, fndn, hse, #2806 at gro	le Transformer pole le 24" Willow S 30°	N 05° W 47.24' E 57.10'	,	KOL	NDY J. EHOUSE	

Landy of the her

25854

Surveyor's Michigan License No. \_\_\_

FORM APPROVED BY MICHGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983