В.

C.

Surveyor's Michigan License No.\_

MAR 03 1998

•	KEN! COONT! KEMONUMENTATION	1 -3 32
SECTION	LAND CORNER RECORDATION CERT	TIFICATE OF C TO SOCIAL
For corners in	Filing Requirement of Act 74, Mich. P.	A. 1970 o f. l n 円蓋位
KENT COUNTY		
Located	d in: Corner Code #	
(County)		は
1. Public Land Survey	T 6N R 9W . C-7	
	TR	
••	TR	· ,
0 Promote 0 1 10	TR	
2. Property Controlling S in Section S S	<u>TR</u>	
3. Miscellaneous	<u>'</u> κ	9805
Property in Sec.	TR	0000
		Register of Deeds Stamp & File Number
A Lot No.		
4. Lot No, Recorded Plat _ 5. Private Claims		. B B C B B B B B
· · · · · · · · · · · · · · · · · · ·		A B C D E F G H I J K :
		2 - 6 - 5 - 4 - 3 - 2
Kirk Breitels	Jan. 30 97	3
	survey on, 19 do hereby state that un 10, the corner points mentioned in lines 1 and 2 above were	
that the corner points mentioned in lines 3.4 as	u of Land Management or by a decree of a Court of Law and	1/or 6 18 17 16 15 14 1
Taria calicios of by a Decise (i	a Court of Law, established, re-established, monument	gan 7 ted. 7
recovered, found as expressed below:		8 19 20 21 22 23 2
NOTE: Not more than 2 corners, all in the	same town and range, may be recorded	9
on this certificate.		10 30 29 28 27 26 2
,	! .	11
	i di	12 31 32 33 34 35 3
A =		13
A. Description of original monument and	accessories and/or subsequent restoration:	
C-7 1830 GLO	Mullett Set Post	
1934 Kent Co. Wit	t. Plow Point &	& Stone
1977 LCRC #1017	McCombs 3/4" Pipe	
1977 LCRC #1088 1981 LCRC #2263	VanKooten 1" Iron	
1995 LCRC #8179	Merdinski Set Kent Cou Breitels Kent County	Inty Monument
The position of this corn	er was previously approved by the	Kont County Domanimantation
Peer Group, monumented by	John A. Merdzinski on 6/19/81 and	Was recorded per LCRC #2263
C-7 Found standard Kont	and/or method applied in restoring or reestablishing	corner:
John A. Merdzinski in pl	Co. Mon. (Harrison) per witnesse ace of the 3/4" Iron, Plow Point	s from above LCRC as set by
CHECK WITH VOHE CO. WIT.	and LCRC's #1017 & #1088.	and Scone he Toung. All
<u>LCRC_#2263</u>	LCRC #8179	•
	S20°E 65.90' Nail & tag P. P	
	S70°E 124.11' Nail & tag 42" N40°W 76.85' Nail & tag 24"	
	N40°W 76.85' Nail & tag 24" North 45.74' Nail & tag 18"	· ==
NW cor. hse. #10416	$S45^{\circ}E$ 116.72' NW has cor #1	DA16 SAEOE 116 70'
The selected location is	accepted by me and is generally	V accompand by management
C-7 Standard Kent County !	frable evidence of the position of accessories established to perpetuate locating the position of the position	position of the corner:
Nail & KC Remon. tag	W. side P. Pole S20°E 65.75	
Nail & KC Remon. tag	N. side 42" Oak \$70°F 123 42	MARKET TO A STATE OF THE STATE
Nail & KC Remon. tag	E. side 24" Oak N40°W 77 02	
Nail & KC Remon. tag	E. side 18" Cherry N00°E 45.86	KIRK BEETELS
NW cor. hse. #10416	S45°E 116.72 is 1' South; On tree line North	LAND
o. dage of payement	o Tourn, on tree line North	SURVEYOR
/		30077
1/10 0	<i>/</i>	1-
igned by / Luh Bun H.	<u></u>	KIRK BEEITELS LAND SURVEYOR NO 30077
	Data 4	

P.A. 345 1990 KENT COUNTY PEER APPROVED 3/27/9

30077

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995