REMONUMENTATION

MAR 03 1998

SECTION

KENT COUNTY REMONUMENTATION

		Requirement of A			•		97 97	,
For corners in	•	•	•	1	j	RFG		
KENT COUNTY	Located in:	Corner Code #					ると	
(County)					 مدي		<u> </u>	국유
1. Public Land Survey	T 6N R 9	9W J−3			[7] [7]	1/20		MAT MAT
	TR_				Č.	100	යා <u>පූ</u>	71 H
•	TR_					سخر.	22 ORG	-1 D-
2. Property Controlling	s tR_						.44	Å.
in Section	s				986	5	•	* 1.7
3. Miscellaneous	S TR_	•			300	O		
Property in Sec.	3 IR_				Register o	of Deeds S	tamp & File	Number
_						•		
4. Lot No, Reco 5. Private Claims					ч в с	D E F	G H I	JKLM
5. Fivale Cidins				2		5 4 -	3	2 1
•				.3	_ <u> </u>	Ĭ	<u> </u>	
Kirk Breitels	, in a field survey on	<u>Jan. 16</u> , 19 <u>97</u> d	lo hereby state that u	ınder 4		89	10	11-12
requirements of P.A. 74, Michig conformance with regulations and	an P.A. of 1970, the corner	points mentioned in line	es 1 and 2 above we	rein _		<u> </u>		
United States Department of the	Interior, Bureau of Land Ma	nagement or by a decree	of a Court of Law an	id/or 6	18		15	14——13—
that the corner points mentioned Board of Land Surveyors or b							 -	
recovered, found as expressed b	elow:			8	1 9	2021	222	23 24
NOTE: Not more than 2 cor	ners, all in the same town	and range, may be rec	corded	9 -		 	++-	
on this certificate.				10	302	2'9——2'8— 1	27-2	2625
			•	11				<u> </u>
		·		12	31	32 <u> </u>	34 3	1536
A. Description of original me	onument and accessorie	s and/or subsequent :	restoration:	13		· · · · · · · · · · · · · · · · · · ·		
•		Mullett	Set Post					
	C #4492	VanKooten	Rerod	;				
	C #5857	Bueche	Set Kent Co	ounty Mo	onument			
The position of Peer Group, monu	this corner was mented by John (previously app C. Bueche on 6	proved by the -13-91 and v	e Kent vas reco	County orded p	Remonum er LCRC	entation #5857.	a,**.
		:						•
B. Description of corner ev	idence found and/or met	thod applied in restorit	ng or reestablishin	g corner:	ļ		. v.	
J-3 Found stand John C. Bueche i with LCRC #4492. LCRC #5857	n place of the F	n. (Harrison) lerod he found	per witness over a seco	es from nd Rero	n above d. Bot	LCRC a h Rerod	s set by s checks	y s
Center W. gate		S80°E	57.90'		-			
	SÉ side old P.	Pole N40°E N70°W	66.88' 127.99'					
PK Nail S. side		N70°E	127.14	*			,	
On asphalt road	l to fairgrounds	, 2' North of	South edge					7
The selected lo	cation is accep	ted by me and	i is genera	lly acc	epted	by pror	essiona er	1
surveyors as the C. Description of monument	e pest available t for corner and accesso	ries established to per	rpetuate locating t	he position	of the cor	ner:		
J-3 Standard Ke	ent County Monume	ent				وجومي		
Center W.	gate post @ base	a Id D. Dolo		57.85'. 56.78'	*	6	F 6.6	Mr.
	anail SE side o' side P. Pole	ia P. Pole		27.99'	: 4	The same	Principal Control	
PK Nail S.	side P. Pole		N70°E 12	27.14			Kirk 3	* * *
Nail & KC	Remon tag NW s	ide new P. Pol		35.25°		× L	AND .	* 2
On asphalt	road to fairgre	junus, z Nort	n or south (-uye		··· '4	RVEYOR	
				1		· %	0077	
1/1	2 11			,	<i>1</i> .		CALL SECTION OF STREET	10 10 10 10 10 10 10 10 10 10 10 10 10 1
Signed by Kuly	Truth		Date	3/27/	197	The state of the s	180	
Surveyor's Michigan License	00077			:				
	110							
PEER APPRO	O KENT COUNTY		FORM APPROVED BY	MICHICAN ST	ATE BOARD O	F PROFESSION	NAL SURVEYOR	RS, JAN. 28, 1971
CHAIRMAN		To a c	, with the Charles of		= = = = = = = = =		REVISE REV	ED MAY 14,1975 VISED JAN., 1983
CHAIRWAN	any forest						REV	ISED OCT., 1995

大きないのでは、自然をは、これに対象が構造の構造がある。おおり、またいできた。これがあるます。