## SURVEY & REMONUMENTATION.

MAR 0 3 1998

KENT COUNTY REMONUMENTATION

n
---

For corners in

**SECTION** 

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

REG. OF	97 APR 29	RECEIVED F
DEEDS	AM 8: 24	OR REDORD

KENT COUNTY	Located In:	Corner Code #
(County)		
1. Public Land Survey	T <u>GN</u> R_ TR_	9W K-1
2. Property Controlling	TR_ TR_ S TR	
in Section  3. Miscellaneous  Property in Sec.	S TR_ S TR_ S TR	


9871

Register of Deeds Stamp & File Number

4. Lot No,	Recorded Plat	•	
5. Private Claims			

, in a field survey on Jan. 30 . 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

K-1	1830	GLO	Mullett	Set Post
	1939	Williams & Works		"City Iron"
	1965	Williams & Works		Conc. Mon. replaces "City Iron"
	1975	LCRC #901	Fluharty	Conc. Mon.
		Kent Co. Wit.	Ų.	Iron
-	1991	LCRC #5768	Chettleburgh	Set Kent County Monument
	1995	LCRC #8290	By1	Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Thomas Chettleburgh on 3/1/91 and recorded per LCRC #5768. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

K-1 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Thomas Chettleburgh on Twp. line in place of the Conc. Monument he found. Said Conc. Monument checks with Williams & Works & LCRC #901.

							~ -~	~~						•	
CRC	#5768	K-13 (	KC Mor	n.)	-	East	92.40'	LCRC	#8	290	K-1	3 (KC	Mon.)	East 92.40	3
KC	Remon.	tag E.	side	9"	0ak	N16°E	36.91	Nail	&	tag	12"	0ak	N16°E	36.95'	
KC	Remon.	tag NW	side	11"	0ak	N49°E	10.89	Nail	&	tag	14"	0ak	N49°E	10.97	
KÇ	Remon.	tag N.	side	15"	0ak	S84°E	16.85	Nail	&	tag	18"	0ak	S84°E	16.94'	
KC	Remon.	tag E.	side	16"	0ak	S01°E	27.46	Nail	&	tag	18"	0ak	S01°E	27.53'	
KC	Remon.	tag S.	side	19"	0ak	N85°W	11.57	Nail	&	tag	22"	0ak	N85°W	11.59'	
ha	anlanta.	d 1000+	ion i	: ~ ~	~~~~+	عدام لمم							والمسالة		-

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

K-1 Standard Kent County Monument

Nail	& KC	Remon t	ag E.	side	12"	0ak	N16°E	36.95'	
Nail	& KC	Remon t	ag NW	side	14"	0ak	N49°E	10.91	
Nail	& KC	Remon. t	ag N.	side	18"	0ak	S84°E	16.89'	
Nail	& KC	Remon. t	ag E.	side	18"	0ak	S01°E	27.53	
Nail	& KC	Remon. t	ag S.	side	22"	0ak	N85°W	11.59'	
K-13	(Kent	t Co. Mon	ı.) T7	N, R91	V		N90°E	92.40'	

KIRK BARITELS LAMD SURYEYOR 30077 4 点的第 \* consequences and

Surveyor's Michigan License No.

30077

P.A. 345 1990 KENT COUNTY PEER APPROVED 3/27/9/

CHAIRMAN

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1985