SURVEY & REMONUMENTATION

MAR 0 3 1998

3	KENT COUNTY REMONUMENT	ATION
SECTION	LAND CORNER RECORDATION	· · · · · · · · · · · · · · · · · · ·
For corners in	Filing Requirement of Act 74, Mich.	P.A. 1970
KENT COUNTY		7/1/23 BEH
(County)	ted In: Corner Code #	A 258
1. Public Land Survey	T 6N R 9W M-11	
	T N R 9W M-11	
1	T R	7 5 -
Property Controlling S in Section S	TR	
3. Miscellaneous	T R	0000
Property in Sec. S	T_R	9898
4 Lot No.		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat _		
		A B C D E F G H I J K L
Kirk Breitels		2 - 6 - 5 - 4 - 3 - 2 - 1
requirements of D.A. 74 Att	survey on Jan. 6, 19 97 do hereby state that 70, the corner points mentioned in lines 1 and 2 above we as required in the current manual of survey.	under 4 7 8 3
United States Department of and rules therefor	re as required in the current and 2 above w	ere in (1 1 1 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1
Board of Land Surveyors or by a Decree of	tu of Land Management or by a decree of a Court of Law at and 5 above were in conformance with the rules of the Mici f a Court of Law; established re-established	nd /or 6 18 17 16 15 14
as sopiessed below.	to established, monume	nted, 7
NOTE: Not more than 2 corners, all in the on this certificate.	same town and range, may be recorded	8 -19 -20 -21 -22 -23 -24
on and ceruncate.	J. Hard Recorded	10 30 29
		11 28 27 26 25
A Deportation of the		12 -31 - 32 - 33 - 34 - 35 - 36
M-11 1830 GLO	accessories and/or subsequent restoration:	13
M-11 1830 GLO 1966 Kent Co. Wit	Mullett Set Post	
1979 LCRC #3362	1/2" Iron i	n Mon. Box
1995 LCRC #8873	Jonker Set Kent Co.	11n + 1 2 2 4
The position of this corne	er was previously approved by the Robert J. Jonker on 12/20/95 and	word more the won. Box
reer droup, monumented by	er was previously approved by the Robert J. Jonker on 12/20/95 and	Was recorded per Long was recorded per Long was
B. Description of corner evidence found		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
M-11 Found standard Kent	nd/or method applied in restoring or reestablishing o	corner:
Ropert J. Jonker in misse	mail (Soil) per witnesses	from above LCRC as set by
LCRC #8873	III Co. Wit. and LCRC #3362.	side a Mon. Box. Said Pipe
Nail & KC Remon. tag S. s	ide P. Pole S70°E 26.23'	
Nail & KC Remon to SE's	ide P. Pole N37°E 45.72	
, and the transfer it	Mp. corner) North 25.47'	
The selected 1-		
C. Description of monument for corner and as	accepted by me and is generally able evidence of the position of ccessories established to perpetuate locating the produced in Mon. Box	accepted by professional
M-11 Standard Kent County M	control established to perpetuate locating the per	osition of the corner:
Nail & KC Remon. tag Nail & KC Remon. tag Nail & KC Remon. tag	C and a management	
"~" W NU BENIOD Tag	0 -3-1	
1/2" Pipe (A-11, Bosto	on Twp. corner) North 25.47	KIRK
		BABITELS LAND
	15 	SURVEYOR NO
1/1/2/1		30077
Signed by Knh Mitts		1-1
Surveyor's Michigan License No. 30077	Date	27/97
P.A. 345 1990 KENT CO	UNTY	
PEER APPROVED 3/2	7/9/	
CHAIRMAN Pany	Kuhele Form APPROVED BY MICHIGA	N STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
		REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995
THE PROPERTY OF THE PROPERTY O		- 4