FFB 1 4 1997

KENT COUNTY REMONUMENTATION

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1. Public Land Survey

KENT COUNTY

(County)

For corners in

T6N R 10W

Corner Code#

8956

2. Property Controlling in Section 3. Miscellaneous Property in Sec.

Located in:


Register of Deeds Stamp & File Number

\_, Recorded Plat 5. Private Claims

Feb. 6, 19 96 do hereby state that under Kirk Breitels in a field survey on \_ requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in requirements of First 1-7, internigent First of 1970, the conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan

Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Set Post Mullett 1831 GLO 1/2" Iron

3/4" Iron

PEER APPROYED 3/7/9 CHAIRMAN

Kent Co. Wit. LCRC #470 1973 LCRC #1888 1981 LCRC #4395 1986

Spicer Merdzinski Chettleburgh

Set Kent County Monument Kent County Monument

Kent County Monument LCRC #7112 Bueche 1994 The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by John A. Merdzinski on 6/2/81 and was recorded per LCRC #1888

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-7 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by John A. Merdzinski in place of the 1" Iron he found. Said Iron checks with Kent Co. Wit. and LCRC #470.

LCRC #1888 (Nail & tag)

12" Basswood S55°E 47.27'

MBT Pole East 48.40' 12" Oak N50°E 57.99' Oak N20°W 62.09' 12" Oak N85°W 34.0'

8" Oak \$25°W 49.30'

30077

LCRC #4395 & #7112 (Nail/tag)

MBT Pole East 48.40' 14" Oak N50°E 57.85' 16" Pine N50°E 78.14'

NE cor. CB casting S25°W 31.48' NW cor. CB casting S41°E 41.64'

C/L Manhole

\$10°E 32.45'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

E-7 Standard Kent County Monument

Nail & KC Remon. tag S. side MBT Pole Nail & KC Remon. tag NW side 14" Oak 48.40 East N50°E 57.85 Nail & KC Remon. tag NW side 16" Pine N50°E 78.14 S25°W NE corner catch basin casting 31.48 S41°E 41.64' NW corner catch basin casting S10°E 32.45 C/L Manhole C/L bit. road North-South is East 8.3'+

KIRK BREITELS LAND SURVEYOR МĐ ONET OF

Signed by

Surveyor's Michigan License No.