## SURVEY & REMONUMENTATION

FEB 1 4 1997

## KENT COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
For corners in  KENT COUNTY  Located In:  COMMISSION Filling Requirement of Act 74, Mich. P.A. 1970  Located In:  Corner Code #
(County)
1. Public Land Survey  T 6N R 10W T R T R T R T R
2. Property Controlling S T R
Droporty in Son
Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat
Kirk Breitels , in a field survey on Feb. 22 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:
NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate. 10 30 29 28 27 26 25
11
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
A. Description of original monument and accessories and/or subsequent restoration:
K-3 1831 GLO Mullett Set Post P.A. 345 1990 KENT COUNTY
Kent Co. Wit. Witnesses given PEER APPROVED 3/7/86
1978 LCRC #1110 Bonnema 3/4" Iron CHAIRMAN facult future 1982 LCRC #2747 Merdzinski Set Kent County Monument
1991 LCRC #6094 Unema Kent County Monument
The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by John A. Merdzinski on 2/18/82 and was recorded per LCRC #2747  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
K-3 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by John A. Merdzinski in place of the 3/4" Iron he found. Said Iron checks with LCRC #1110. No Kent Co. Wit. remain.  LCRC #2747  LCRC #6094
Nail/tag Twin 12" Oak S10°E 30.8' Nail/tag 22" Oak N45°W 6.36' Nail/tag 10" Oak S30°W 34.7' Nail/tag 12" Oak N65°E 20.20' Nail/tag 22" Oak N45°W 6.38' Nail/tag 12" Oak S80°E 34.54' Nail/tag 10" Oak N65°E 20.20' Nail/tag Twin 12" Oak S10°E 30.82'
Nail/tag 10" Oak N65°E 20.20' Nail/tag Twin 12" Oak S10°E 30.82' Nail/tag 10" Oak S80°E 34.55' Nail/tag 12" Oak S30°W 34.68'
The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.
V. 2. Standard Vent County Manument
Nail & KC Remon. tag S. side 26" Oak N45°W 6.36' Nail & KC Remon. tag SE side 14" Oak N65°E 20.20' Nail & KC Remon. tag N. side 14" Oak S80°E 34.54' Nail & KC Remon. tag E. side Twin 14" Oak S10°E 30.82' Nail & KC Remon. tag E. side 14" Oak S30°W 34.68' On old fence line E-W  Signed by  Date 3/1/96
Nail & KC Remon. tag E. side 14" Oak S30°W 34.68'
On old fence line E-W
O LAND S
Signed by / Lut Bu Lo Date 3/1/96
Surveyor's Michigan License No. 30077