SURVEY & REMONUMENTATION



KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

APR 27 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE 94 DEC -5 MM 8: 54
Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in KENT COUNTY				,, I ·	Luchan	. "
. —	(County)	Located	in:	Corner Code =	#	REG. OF DEEDS	
1.	Public Land Survey	T T	R <u>11W</u> R R R	B-13		HEST OF DEEDS	
2.	Property Controlling		R			7611	
3.	Miscellaneous	S T		approximation and the second		Register of Deeds Stamp & F	ile Number
	Property in Sec.	S T	_ R			. *	
4.	Lot No	, Recorded Plat				— A B C D E F G	ніјкь
5.	Private Claims						3
						3	
						4 7 8 9	101
1	William R. By	/1 , in a field survey o	n0	ct. 6	19 <u>94</u> ,	5	
in f	ines 1 and 2 above we	er requirements of P.A. 74, are in conformance with r	egulations and	rules therefore as r	equired in the	6 - 1/8 - 1/7 1/6 - 1	1514
		nstructions of the United e of a Court of Law and/or				7 8 19 20 21	
abo	ove were in conformance	e with the rules of the Mic	higan Board of L	and Surveyors or by	y a Decree of a	9 19 20 21	22 23 2
	urt of Law; establishe pressed below:	ed, re-established, monu	mented, re-mo	numented, recover	ed, found as	10 30 29 28	27 26
		4 corners, all in the sa	ame town and	range, may be re	corded	11	
	on this certific					12 31 32 33	34353
Α.	Description of origin	nal monument and acc	essories and/o	or subsequent res	toration: D A	L 345 1000 KENT COUNT	Y
Λ.	Description of ongi		ESSONES UNG	or subsequent ree	DE:	ER APPROVED/12/1/	94
	B-13 1831	GLO	Mulleti		036	IAIRMAN Hawy	Lufu
	1974	Kent Co. Wit. LCRC #656	Spicer	1" Ir Set E	on On K Nail fr		
	1981	LCRC #1689	Merdzi			y Monument	
	1992	LCRC #6493	Bueche			inty Monument	
						ent County Remonument as recorded per LCRC	
	reer droop, n	ondinenced by both	II A. Meruz	111361 011 2/20	,, or and w	as recorded per condi-	1003
_	Description of som	er evidence found and.	or mathad an	nlied in restoring	or ropetablish	hina cornor	
₿.						from above LCRC as se	et hv
						in 1981 in place of the	
		d. PK Nail check	ced with Lo		100		
	LCRC #1689 Nail & KC ta	ag 60" Cottonwood	1 N32°W 130	LCRC #6	<u>9493</u> . brick h	se. #402 S15°E 112.	921
	Nail & KC ta	ng 10" Pine	N50°E 117	7.91' E & N	line of w		
		ng Tri. 10" Maple			line of w		
	NW cor. fnd.	k garage #410 hse #408	S55°E 138.		fnd. hse	r. hse. #410 S55°E 130 e. #408 — S30°E 9	3.72° 7.04°
		ige, hse. #400				_	3.35'
	C/L MH	(03)				; C/L Bit. Rd. N., E.	29'
		(Blktp.) South				6-5-11) W. 29.04' accepted by profess:	ional
	surveyors as	the best availab	ole evidend	ce of the pos	ition of	the original corner.	
Ç.				tablished to perpe	etuate locatin	ig the position of the corner:	
		! Kent County Mor brick hse. #402	ument	S15°E 112	.99'		
	E & N 11	ne of walks		N45°E 82	.05'	and the second	
		ne of walks			.42'	William R	N. T.
		brick garage, he find. hse. #408	e. #410		.68' .04'	# / Byl	7 × 3
		brick garage, he	e. #400		.35'	Registered Le	nd T
		(N 1/4 cor. Sec.	•		.94'		
	On C/L 6	60th St.; C/L Bit	7 Rd. N.,	E. 29'		23502	

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN.. 1983