





STATE OF MICHIGAN COUNTY OF KENT REČĔĬVĚĎ FŎŔ ŘĔĊŎŖĎ

APR 2 7 1995

For corners in COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC -5 AM 8: 54

Corner Code ##

KENT COUNTY Located In: (County) T 6N R 11W 1. Public Land Survey ____ R __ T _____ R _ ___ T ____ R _ 2. Property Controlling S ____ T ___ R _ in Section S _____ T ____ R ____ 3. Miscellaneous __ T ____ R _ Property in Sec.

 $_$, Recorded Plat $_$

Register of Deeds Stamp & File Number

5. Private Claims

William R. Byl in a field survey on _ Sept. 21 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in fines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

8 9 10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

P.A. 345 1990 KENT COUNTY

C-3	1831	GLO	Mullett	Set Post	PEER APPROYED	12/1/	94
	1920	Williams & Works		City Iron	CHAIRMAN Ta	0/	.h.
	1957	City of Grand Rapids		City Ilon		my/pl	N/C
		Kent Co. Wit.		No desc. of	corner-witnesses	gviven	* \$
	1984	LCRC #3771	By1	Set Kent Co	unty Monument		
	1992	LCRC #6495	Bueche	Kent County	Monument		

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by William R. Byl on 2/13/84 and was recorded per LCRC #3771

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-3 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by William R. Byl in place of the City Iron he found. Said City Iron checks with City of Grand Rapids witnesses.

LCRC #3771

LCRC #6495 SE cor. brick ven. bldg. #757 N45°W 97.63' same witnesses as LCRC #3771

\$40°W NE cor. stucco bldg. #758 49.43' Face of 4" steel post S45°E 46.94 cut top SW bolt traffic

signal pole N45°E 45.46'

Easterly rim of sewer manhole S85°W

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-3 Standard Kent County Monument

SE cor. brick veneer bldg. #757 N45°W 97.633 NE cor. stucco bldg. #758 Face of 4" steel post @ sidewalk S40°W 49.47' S45°E 47.01' "X" cut top SW bolt traffic signal pole N45°E 45.447 \$85°W Easterly rim of sewer manhole

wittem R By1 Registered Land Surveyor No. 1424

Surveyor's Michigan License No.

_____ Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983