









APR 2 7 1995

KENT COUNTY REMONUMENTATION

## COMMISSION

\_ , Recorded Plat \_

4. Lot No.

5. Private Claims

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STA CC RECE	ATE CI JUNTY VED F	1410 0F }	HIG	AN T
94 DE(	C-5	AH	8:	UKO 55

REG. OF DEFOS

7623


Register of Deeds Stamp & File Number

For corners in					
	KENT COUNTY (County)	Located In:	Corner Code ≠#		
1.	Public Land Survey	T 6N R 11W	C-12		
		T R T R			
		T R			
2.	Property Controlling	S T R			
	in Section	S T R			
3.	Miscellaneous	S R			
	Property in Sec.	S T R			

I, William R. Byl, in a field survey on Sept. 16, 19, 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:



P.A. 345 1990 KENT COUNTY

				DEED ADDS	_
C-12	1831	GLO	Mullett	Set Post PEER APPR	•
0 12	1001	uLO	Mullett.		
	1974	LCRC #707	Bonnema	3/4" Iron CHAIRMAN	_
	1982	LCRC #2996	By1	Set Kent County Monument	
	1992	LCRC #6504	Rueche	Kent County Monument	

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by William R. Byl on 5/20/82 and was recorded per LCRC #2996

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-12 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by William R. Byl in place of the 3/4" Iron Pipe he found. Said Iron Pipe checks with LCRC #707.

<u>LCRC #2996</u>		LCRC #6504		
Nail & tag P. Pole	S85°E 36.50'	Nail & KC Remon. tag S. side PP	\$85°E	36.50'
SE cor. gar. fdn.	N45°W 109.14'	SE cor. gar. fnd. Hse. #781		109.14
		NE cor. gar. fnd. Hse. #5619	S40°W	130.55
NW cor. brk. planter	S40°E 79.17'	NW cor. brick planter	S40°E	79.17
		NW cor. of header of CB	N17°W	82.56
		NE cor. of header of CB	N17°E	80.11'
		On C/L Bit. Rd. N-S-W		

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-12 Standard Kent County Monument Nail & KC Remon. tag S. side P. Pole S85°E 36.58' SE cor. gar. fnd. Hse. #781 N45°W 109.14' NE cor. gar. fnd. Hse. #5619 NW cor. brick planter \$40°W 130.55 S40°E 79.20' NW cor. of header of CB N17°W 82.56' NE cor. of header of CB N17°E 80.11' On C/L Bit. Rd. N-S-W

Winterm R.
Byd

Hogostared Land
Substitute

No.
23502

Signed by

Surveyor's Michigan License No.

\_ Date \_\_\_\_\_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

REVISED JAN., 1983