## SURVEY & REMONUMENTATION



KENT COUNTY REMONUMENTATION

## STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

## COMMISSION

APR 27 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC -5 AM 8: 56

June	Lacket.
REG. OF	DEEDS

KENT COUNTY (County)		Located In:	Corner Code ##	
		Located III.		
1.	Public Land Survey	T <u>6N</u> R <u>11W</u>		
		T R		
		T R		
		T R		
2.	Property Controlling	S		
	in Section	S T R		
3.	Miscellaneous	S T R		
	Property in Sec.	S T R		

\_\_\_ Recorded Plat \_\_\_

5. Private Claims

7630 Register of Deeds Stamp & File Number

I, William R. Byl, in a field survey on July 7, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

5 6 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

P.A. 345 1990 KENT COUNTY
PEER APPROVED 12/1/94
CHAIRMAN Vary Mule

D-11	1831	GLO	Mullett	Set Post PEER APP
	1938	Kent Co. Wit.		Concrete Monument CHAIRMAN
	1976	LCRC #939	Merdzinski	1 1/2" Iron
	1982	LCRC #3001	Byl	Set Kent County Monument
	1987	LCRC #4512	Milliron	Reset Kent County Monument
	1992	LCRC #6510	Bueche	Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by William R. Byl on 5/20/82 and was recorded per LCRC #3001

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-11 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Rex Milliron from witnesses used in 1982 by William R. Byl when he set a Kent County Monument in place of the 1 1/2" x 3" Iron Pipe he found over a Concrete Monument. Said Iron Pipe and Concrete Monument checks with Kent Co. Wit. and LCRC # 939.

LURU #3001		<u>LCRC #6510</u>		
Nail & tag P. Pole	NOO°W 43.41'	SE cor. gar. fnd. #1185	N25°W	89.77
SE cor. gar. fnd.		KC Remon. tag & nail W. sd. PP		43.35'
hse. #1185	N20°W 89.76'	PK E. sd. 26" Ash	N30°E	65.18'
SE cor. brick hse. #1213	N55°E 130.58'	SW cor. brick bldg.	N40°E	105.35'
NW cor. brick hse.	S45°E 147.16'		S40°W	71.90'
			S35°W	147.06

On C/L Bit. Rd. E-W; C/L Bit. Rd. S. is E. 24'
The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

D-11 Standard Kent County Monument SE cor. gar. fnd. #1185 N25°W 89.77 KC Remon. tag & nail W. side P. Pole NOOPE 43.42' N30°E Set KC Remon. tag & nail E. side 30" Ash 65.22 SW cor. brick bldg, N40°E 105.35' PK F. root 38" Maple -S40°W 71.90' NW cor. hse. #1212 (brick) S35°W 147.06 On C/L Bit. Rd. E-W; C/L Bit. Rd. S. is E. 24'

112794

Registered Land
Sinversor
No.
23502

Signed by \_\_\_\_

7 ~

\_\_ Date \_