SURVEY & REMONUMENTATION



APR 27 1995

COMMISSION

KENT COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF KENT REČĔĬVĔĎ FŎŔ ŘĔĊŎŖĐ 94, DEC -5 AM 8: 58

Comer Code ##

7678

Register of Deeds Stamp & File Number

For corners in KENT COUNTY Located In: (County) T _6N_ R 11W **Public Land Survey** ____ R ___ **Property Controlling** ___ T ___ in Section S ____ R _ Miscellaneous _ T ___ Property in Sec.

_ , Recorded Plat .

5. Private Claims __

expressed below:

我们的"阿特特拉拉特特特特别"。

William R. Bvl , in a field survey on _ Sept. 6 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

3 10 11 12 13

Description of original monument and accessories and/or subsequent restoration:

P.A. 345 1990 KENT COUNTY PEER APPROYED 12/1/04

1-9	1831	GLO	Mullett	Iron in mon. DOXIRMAN Farry July
	1953	Kent Co. Wit.		Iron in mon. Box in wall from the mon.
	1981	LCRC #2037	Hackbardt	Set Kent County Monument
	1982	LCRC #3189	Wickham	Reset Kent Co. Mon. after road const.
	1989	LCRC #4953	Bueche	Kent County Monument
	1993	LCRC #6764	Roon	Kent County Monument
				وواقي المساوية والأوراء

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Glen S. Hackbardt on 8/27/81 and was recorded per LCRC #2037

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-9 Found standard Kent Co. Mon. (Harrison) inside a mon. box per witnesses from above LCRC as set by Burt Wickham Jr. in the same location as set in 1981 by Glen S. Hacbardt in place of the 3/4" x 18" crimped iron he found inside a mon. box. Said crimped iron checks with Kent Co. Wit. and survey data by others.

<u>I.CRC_#3189</u>	LCRC #4963 & 6764		
N15°W Nail & tag CP Pole 76.86'	Cut mark @ back of curb	N70°₩	36.12'
N30°E Nail & tag Guy Pole 80.34'	Nail & tag Guy Pole	N30°E	76.80'
S65°W Nail & tag CP Pole 79.98'	Nail & tag CP Pole:	S65°W	79.98'
S50°E Nail & tag CP Pole 79.09'	Nail & tag CP Pole	S50°E	79.09'
~	Nail & tag P. Pole	N40°E	84.20'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-9 Standard Kent County Monument in mon. box N70°W Cut mark @ back of curb 36.07 N30°E 76.85 Nail & KC Remon. tag NW side Guy Pole S65°₩ New Nail & KC Remon. tag S. side CP Pole 80.03 Nail & KC Remon. tag N. side CP Pole S50°E 79.07 Nail & MDSH tag SW side P. Pole N40°W 84.16

Signed by Surveyor's Michigan License No.

____ Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

Jem R

BY

Kagistered Land

Surveyor No. 23502

146

REVISED JAN., 1983
