



KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

COMMISSION

Top C/L of hydrant

Surveyor's Michigan License No.

23502

Signed by .

LAND CORNER RECORDATION CERTIFICATE.

94 DEC -5 AM 8: 59

Fo	r corners in	Hillin	ig Requireme	nt of Act 74, Mich.	P.A. 1970
	KENT COUNTY	Located In	·•	Corner Code :##	La Print
_	(County)	Located ii		Comer Code 44	The state of the s
	5 1 No. 1 1 C	T 011	0 445		REG. OF DEEDS
1.	Public Land Survey	T <u>6N</u> T		_K-4	
		T			
		т			
2.	Property Controlling	S T			7693
	in Section	s T			1033
3.	Miscellaneous	S T		· · · · · · · · · · · · · · · · · · ·	Register of Deeds Stamp & File Number
	Property in Sec.	S T	R		
	Lot No ,				A B C D E F G H I J K
5.	Private Claims		<u></u>		2 5 5
					3 1 1 1 1 1 1 2 1
	W4774.m. D. D. 7	in a first account of	A	40 40 4	4 7 4 8 4 10 10 10 10
	William R. Byl hereby certify that under re				ntioned
	lines 1 and 2 above were i				d in the
	rent manual of survey insti		•		
	nagement or by a decree of ove were in conformance w				
	urt of Law; established,		_	•	
exp	ressed below:				10 30 29 28 27 26
NO	TE: Not more than 4 of	corners, all in the san	ne town and ra	nge, may be recorde	d 11
	on this certificate	•	•		12 31 32 33 34 35
					13
Α.	Description of original	monument and acces	sories and/or s	subsequent restoration	on;
					P.A. 345 1990 KENT COUNTY
	K-4 1831 GL	0	Mullett	Set Post	PEER APPROVED/12/1/99
		nt Co. Wit.		PK Spike	CHAIDMANN
		RC #486	Spicer	3/4" Soli	d Iron CHAIRMAN Fay Mule
		RC #2029	Hackbardi	t Set Kent	County Monument
		RC #5729	Bueche		County Monument
	ine position of	this corner wa	s previous!	y approved by t	the Kent County Remonumentation
	Peer Group, mon	umented by Gien	S. Hackbar	at on 6/10/81 a	and was recorded per LCRC #2029
					•
В.	Description of corner e	vidence found and/o	r method applie	ed in restoring or rees	stablishing corner:
	K-4 Found stan	dard Kent Co A	ion (Harri	con) nor witne	sses from above LCRC as set by
	John C. Bueche	at the same loca	tion as set	t in 1981 hv Gl	en S. Hackbardt in place of the
	1/2" x 6" boat s	spike and 3/4" i	ron he four	nd. Both check	with Kent Co. Wit. & LCRC #486
	LCRC #2029	,	LCRC	#5729	· · · · · · · · · · · · · · · · · · ·
	C/L manhole	S30°E 3		witnesses as	LCRC #2029
	C/L manhole	S30°W 3	B.66'		
	SE cor. brick	bldg. N55°W 10	3.98'	plus	
	C/L manhole	N25°W 5			
	C/L manhole	N40°E 2	7.10' Nail	& Remon. tag !	N. side P. Pole S85°W 52.00'
	The selected lo	ocation is acce	epted by me	and is gener	ally accepted by professional
	surveyors as the	e best availabl	e evidence	of the position	n of the original corner.
		•			
Э.	Description of monume	ent for corner and acc	essories estab	lished to perpetuate	locating the position of the corner:
	V 4 04	-L 0-11-1-1-1-1	d.	į	
	K-4 Standard Kei		ent	0000	
	C/L manhole			S30°E 32.47'	
	C/L manhole	سائمان		\$30°W 38.61'	
	SE cor. brid	ck blag.		N55°W 103 98'	Byl
	C/L manhole			N25°W 59.03'	Registered Land
	C/L manhole	omon taxat of	da D. Dalli	N40°E 27.21'	Willem R. Byl Registered Land Sur-wor No.
	Top C/L of I	emon. tag N. si	ua P. MOIE	S85°W 51.92' N30°W 79.32'	
	I OD O'L OT I	IYUI AIIL		NSU W /9132'	№ 7. 23502

S25°W

92.03

Date

FORM APPROVES BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISEO MAY 14, 1975 REVISED JAN.. 1983

IND