SURVEY & REMONUMENTATION

APR 2 7 1995

Property in Sec.

KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT REČĚĬVĚĎ FŎŔ ŘĚĆÔRD

94 DEC -5 AM 9: 00 LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

REG. OF DEEDS

7695

3

Register of Deeds Stamp & File Number

For corner COMMISSION KENT COUNTY Located In: Corner Code ## (County) 1. Public Land Survey T _6N_ R _11W ____ R ___ _ R _ T _____ R . **Property Controlling** _ T _____ R _ in Section __ T ____ R _ .T.____R. Miscellaneous

__ R __

_ , Recorded Plat _ Private Claims _

T_

William R. Byl, in a field survey on ... Sept. 22 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12 P.A. 345 1990 KENT COUNTY

Description of original monument and accessories and/or subsequent restoration:

K-6	1831	GLO	Mullett	Set Post PEER APPRO
		Kent Co. Wit.		1/0" Tran
	1974	LCRC #694	Bonnema	1/2" Iron CHAIRMAN
	1981	LCRC #2028	Hackbardt	Set Kent County Monument
	1989	LCRC #4967	Bueche	Kent County Monument
	1993	LCRC #6754	Roon	Kent County Monument
				,

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Glen S. Hackbardt on 6/10/81 and was recorded per LCRC #2028

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-6 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Glen S. Hackbardt in place of the 1/2" x 6" Bt. Spike over a 1/4" x 6" conc. nail over a 1/2" x 18" Iron he found. All check with Kent Co. Wit. and LCRC #694.

LCRC #2028 LCRC #4967 & #6754 N75°W 78.86' C/L Hydrant C/L hydrant N75°W N60°W 46.12' C/L Manhole C/L manhole N60°W 46.12' Nail & tag 36" Maple N45°E Nail & tag 26" Maple N80°E Nail & cap 30" Maple N45°E 65.90' 65.90' Nail & cap Tri. 12" Spruce S40°E 52.92' 36.85' Nail & tag 16" Fir S40°E 52.83 Nail & tag P. Pole S45°W 36.84 Nail & tag P. Pole N60°W 81.44'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-6 Standard Kent County Monument

C/L Hydrant N75°W 78.82 C/L Manhole N60°W 46.12 N45°E Nail & KC Remon. tag S. side 36" Maple 65.96 New Nail & KC Remon. tag N. side 26" Maple N80°E 36.85 S40°E New Nail & KC Remon. tag SW side 16" Fir 52.80 Nail & KC Remon. tag P. Pole S45°W 36.89 Nail & KC Remon. tag P. Pole N60°W 81.401

Date



Signed by _

Surveyor's Michigan License No. 23502

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983