

4. Lot No. Private Claims .

## REMONUMENTATION



Kent County Remonumentation

STATE OF MICHIGAR COUNTY OF KENT REČĔĬŸĖĎ FŎŔ ŘĔĊĠŔŨ

APR 2 8 1995

COMMISSION

\_ , Recorded Plat .

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

M 3: 18 94 NOV 29

Kent (County)		Located In:	Corner Code =##		
		Located III.	Comer Code -74		
1.	Public Land Survey	T 6N R 12W	C-4		
		T R			
		T R			
		T R			
2.	Property Controlling	S T R			
	in Section	S T R			
3.	Miscellaneous	S T R			
	Property in Sec.	S T R	<u> </u>		

REG. OF DEED

Register of Deeds Stamp & File Number

		i i
Randy Kolehouse , in a field survey on	April 27	<sub>19</sub> 94
do hereby certify that under requirements of P.A. 74, Michi	igan P.A. of 1970, the co	orner points mentioned
in lines 1 and 2 above were in conformance with regula current manual of survey instructions of the United State		• • • • • • • • • • • • • • • • • • • •
Management or by a decree of a Court of Law and/or that the		
above were in conformance with the rules of the Michigan		

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

		н	C	D	E	F	G	н_	٠,	K	L	, h
2	L	6	Ŀ	 5	L	4-	L	3—		2		
3	_	_	_	Ĺ	<u> </u>	Ĺ	L		Ŀ	Ĺ		Ĺ
4	_	ļ	_	ļ 	L	) 9	L	 10	L_1	1	L.,	2
5	_	_	_	<u></u>	ļ	<u> </u>	_	<u> </u>	_	_		Ĺ
6	_	 18	ļ	  7	<u> </u>	  6—	<u> </u>	15	1	4	  i	3-
7	_	1		L	<u> </u>	L	$\perp$	<u> </u>		Ĺ		Ĺ
ė	ļ.,	 19—.	2	 !0	_2	1	<u> </u>	 22—	2	3	2	4-
9	<u> </u> _	$oxed{\bot}$	ļ	<u> </u>	L	_	$\perp$	$\perp$		_		Ŀ
10	<u> </u> ;	 30	<u>_</u> ;	  9	_2	 28—	<u>L</u> ,	 27—	2	 6	_2	5
11	<u> </u>	<u> </u>	ļ	<b> </b>	Ļ	_	Ļ				Щ	<u> </u>
12	<u> </u> -:	3 1——	3	2	<u> </u>	  3	$\downarrow$	34	_3	5	3	6
13	I	ı	1			ĺ	1					ł

Description of original monument and accessories and/or subsequent restoration:

C-4	1831 1940 1960 1975 1990	G.L.O. Notes Survey Note Survey Note Survey Note L.C.R.C. #5323	L. Lyon Williams & Works Williams & Works Moore & Bruggink John C. Bueche	NA	P.A. 345 1990 KEN PEER APPROVED CHAIRMAN	T COUNTY 9/22/94 my/Kuhur	-
-----	--------------------------------------	-----------------------------------------------------------------------------	---------------------------------------------------------------------------------------	----	------------------------------------------	---------------------------------	---

The position of this corner was previously approved by the Kent County Remonumentation Peer Group monumented by John C. Bueche on 3/20/90 and was recorded per L.C., R.C. #5323.

- 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - Found K.C. Monument per L.C.R.C. #5323 as set by John C. Bueche using survey records from Williams & Works 1940-1960 and Moore & Bruggink 1975.

L.C.R.C. #5323

Remon. tag & nail in S side 12" Ash N 70° W 5.55' Remon. tag & nail in N side 16" Ash N 85° W 38,65'

Remon, tag & nall in S side 12" Ash N 40° W 54.81'

Remon. tag & nail in E side 10" Ash N 15° E 31.12'

Remon. tag & nail in W side 18" Ash S 25° W 34.68' Remon, tag & nail in SW side 24" Ash S 50° E 34,72'

E. edge river W 86' ±

C/L blacktop Indian Mounds Dr. E. 150' ±

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Standard Kent County Monument

Nail & K.C. remon. tag in S side 12" Ash N 70° W 5.55"

Nall & K.C. remon. tag in N side 16" Ash N 85° W 38.65'

Nail & K.C. remon. tag in S side 12" Ash N 40° W 54.81'

Nail & K.C. remon. tag in E side 10" Ash N 15° E 31.12'

Nail & K.C. remon. tag in W side 18" Ash S 25° W 34,68

Nail & K.C. remon. tag in SW side 24" Ash S 50° E 34.72'

E. edge river W 86' ±

C/L blacktop Indian Mounds Dr. E. 150' ±

RANDY J. KOLEHOUSE AND. 25854

Egned by 25854 ∎rveyor's Michigan License No