

REMONUMENTATION

Kent County Remonumentation

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

APR 2 8 1995

LAND CORNER RECORDATION CERTIFICATES NOV 29 AM 9: 18

F	corners in CO	MMISSION	Filing Require	ment of Act 74, I	Mich. P.A. 1970)		:				
	Kent	Locat	ted In:	Corner Code ⊐	#	Lu	2/2:	إعسم	S			
1. F	(County) Public Land Surve	=	N R <u>12W</u>	E-1		REG.	OF DE	EDS				
		T T	R R R							•		•
	Property Controlli n Section	ng S T S T	R R				74	23		,		·
	Miscellaneous Property in Sec.	S T	R R		Re	gister of D	eeds S	tamp	& File	Num	ber	
		, Recorded Plat			1	A 8		E F	G н	ĻŢ	K I	Τ
in line currer Mana above Court	es 1 and 2 above vont manual of survey gement or by a decrease were in conforman	e , in a field surve der requirements of P.A. were in conformance with rinstructions of the Unit ree of a Court of Law and the with the rules of the ined, re-established, mi	74, Michigan P.A. o th regulations and ted States Departm /or that the corner Michigan Board of	rules therefore as re nent of the Interior, Bu points mentioned in li Land Surveyors or by	equired in the ureau of Land nes 3, 4 and 5 a Decree of a	3 4 5 6 -18 7 8 -19 9			-10	14-		13-
NOTE	E: Not more that on this certifi	n 4 corners, all in the cate.	e same town and	range, may be red	orded	11 12 31 13		-33	34	35-		36
	•	ginal monument and a		or subsequent rest	oration:	13						
E-1	1831 1913-55 1939 1978 1982 1985	G.L.O. Notes Survey Records Wit. Map L.C.R.C. #1148 L.C.R.C. #3264 L.C.R.C. #4121	L. Lyon Williams & V K.C. Survey Exxel Engin Hay William Byl	or Iron eering 1/2" ir 1/2" ir Fnd, 1	and Horse Shoe on in Mon. Box on in Mon. Box i/2" Iron in Mon.	PEER A	IAN Z	YED Yaz	8/1,	1 10	14 9 9 14	1/4
	1990	L.C.R.C. #5564	Thomas Sta	rr K.C. N	Monument					-		

The position of this corner was previously approved by the Kent County Remonumentation Peer Group monumented by William R. Byl on 1/3/85,

- Description of corner evidence found and/or method applied in restoring or reestablishing corner;
 - E-1 Found K.C. Monument in approximate C/L of Maynard Avenue running NNE'ly and Southerly per L.C.R.C.'s #4121 & #5564 as set by William Byl in place of an 1/2" iron in monument box over a bt. spike over a 1" iron pipe (24" deep) which he found and checked using Williams & Works survey records and L.C.R.C.'s #1148 and #3264.

L.C.R.C. #4121

L.C.R.C. #5564

Nail & tag S side p. pole N 70° W 25.32' Nail & tag E side 20" Walnut N 10° E 125,30' Nail & tag N side MBT pole #1200 N 90° E 42.44' SW cor. fndn. hse. #1190 N 60° E 128.30'

Nall & K.C. remon. tag S side p. pole N 70° W 25,32' Nail & K.C. remon. tag E side 20" Walnut N 10° E 125.30" Nall & K.C. remon. tag N side MBT pole #1200 N 90° E 42.44 SW cor. fndn. hse. #1190 entry N 60° E 128.30°

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original comer.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - E-1 Standard Kent County Monument

Nail & K.C. remon. tag S side p. pole N 70° W 25.32' Nail & K.C. remon. tag E side 20" White Oak N 10° E 125.30" Nail & K.C. remon. tag N side MBT pole #1200 N 90° E 42.44° SW cor. fndn. hse, #1190 entry N 60° E 128.30' Nall & K.C. remon, tag N side 16" Elm N 80° W 80.35"



Surveyor's Michigan License No.

25854