

## SURVEY & REMONUMENTATION

Kent County Remonumentation

RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE of, 110U 20 AM 9: 23

	APR 2	8 1995	Filing	Requiremen	nt of Act 74, Mich. I		HUN CO	1311 3	. ( <b>.</b> .		,
For corners in COMMISSION		Located In:		Corner Code ##		Tui Zoland					
	(County)				•	,	REG. 0	F DEED!	3		
1. Pt	ublic Land Survey		T <u>6N</u> R T R T R		l-12						si da
2 0.	onadu Cantrallin		TR TR								
	operty Controlling Section							747	3		
	iscellaneous	s	T R			Regist	er of Dee	•		Numb	er
Pr	roperty in Sec.	S	T R								
<i>A</i> 1 a	ot No	Dopardad	Dist								
	ivate Claims						A B C	DEF	G H	H L I	( L M
J. 11	ivate Ciamis	······································			· · · · · · · · · · · · · · · · · · ·		6	54-		<del> </del>	<del></del> ∔-∤
						. 3	·}}-	┦╌╂╾╏╴		┾┼	╁┷╁┷
				35 a mala 20		. 4	<del></del>	å			<del> </del>
	Randy Kolehouse		d survey on		) 19 94 0, the corner points men		<b> </b>	<del>                                     </del>		<del>├-</del> ├-	╂╼┼
Court expres	of Law; establishe sed below:	ed, re-establis 4 corners, a	hed, monumer	ited, re-monun	Surveyors or by a Decremented, recovered, founge, may be recorded	nd as	30	29 - 28 -	27-	26-35-	25 36
					ubecquest restarction	13		Щ.			<u> </u>
	· -				ubsequent restoration Set Post	n: P.A. 3	45 1990	KENT (	CUNT	Υ	, /
I-12	1948 Sui 1949 Wit 1972 L.C 1981 l4#	O. Notes rvey Records . Map c.R.C. #278 1831 c.R.C. #4693	K.C. S Meder Exxel	n ns & Works urveyor na Van Kooter Engineering Bueche	Iron Iron Square Spike	CHAIR	APPROV MAN	/-/	[28] Y	199 Lu	- bei
-	This corner w Engineering, lo				nty Remonumentation I.C. #1831.	Peer Group	and mor	umented	by Ex	xel	
B. De	escription of corn	er evidence f	ound and/or r	nethod applie	d in restoring or rees	tablishing cor	ner:		•		
1-12	Found K.C. N Engineering in records of 194	place of a so	Burlingame A quare spike w	wenue and 5 hich they foun	6th Street per L.C.R d and which checks L	i.C.'s #1831 a C.R.C. #278	and #4690 of Willian	3 as set ns & Wor	by Ex ks surv	xel ′ey	****
		L.C.R.C. #183	31		L.C	C.R.C. #4693					
•	"X" cut mark S			6'	"X" cut in top of cu	ırb N 68° E 39				:	
	Mail in battle a	an in Wi cide t	note N 200 F	RE 141	"Y" cut mark S sid	MH rim N	760 W 40 1	l 6,			

"X" cut in top curb S 44° E 41.26' On C/L of roads to N, S, & E, on C/L brush row W The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**I-12** Standard Kent County Monument

Top of hydrant N 73° E 75.20

Nail & bottle cap in S side p. pole N 80° W 33.38' "X" cut in top of curb N 68° E 39.70' "X" cut mark S side M.H. rim N 76° W 42.16" Nail in bottle cap in W side t. pole N 20° E 85.14' Top of hydrant N 73° E 75.20' "X" cut in top curb \$ 44° E 41.26" On C/L of roads to N, S, & E, on C/L brush row W

KOLEHOUSE URVEYOR STO LAND SUR

25854 urveyor's Michigan License No.

Nail in bottle cap in W side t. pole N 20° E 85.14'

Top of hydrant N 73° E 75.20'