7

SURVEY & REMONUMENTATION





STATE OF MICHIGAN COUNTY OF KENT

RECEIVED FOR RECORD

APR 28 1995

Kent County Remonumentation

COMMISSION

LAND CORNER RECORDATION CERTIFICATE, HOV 29 AM 9: 24 Filing Requirement of Act 74, Mich. P.A. 1970

Kent	Located In:	Corner Code ≠≠	Luc Bond
(County)		Johnsi Gode 44	REG. OF DEEDS
Public Land Survey	T <u>6N</u> R <u>12\</u> T R T R		NEG. OF DELDO
2. Property Controlling in Section	S T R S T R		7494
3. Miscellaneous Property in Sec.	S T R		Register of Deeds Stamp & File Number
do hereby certify that under req in lines 1 and 2 above were in current manual of survey instru Management or by a decree of a above were in conformance wit Court of Law; established, re expressed below:	in a field survey on uirements of P.A. 74, Michigan conformance with regulation ictions of the United States De Court of Law and/or that the c the rules of the Michigan Boa e-established, monumented,	April 27 , 19 94 P.A. of 1970, the corner points mentils and rules therefore as required in partment of the Interior, Bureau of omer points mentioned in lines 3, 4 and of Land Surveyors or by a Decreate-monumented, recovered, found and range, may be recorded	in the Land 7 and 5 8 19 20 21 22 23 24 se of a nd as 10 30 29 28 27 26 25
on this certificate.		and/or subsequent restoration	12 31 32 33 34 35 36
	•	1 8	

- 1 This comer was not originally set by the G.L.O.

1912-1957 1984 Survey Records

L.C.R.C. #4127

Williams & Works

William R. Byl

City Iron

Fnd. 1" Iron/Set K.C. Mon.

The position of this corner was originally approved by the Kent County Remonumentation Peer Group and monumented by William Byl on 11/28/84 and was recorded per L.C.R.C. #4127.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - L-1 Found K.C. Monument per L.C.R.C. #4127 in imbankment of Highway U.S. 131 as set by William Byl in place of a 1" x 36" iron he found which checked Gov. Dist. East of S 1/4 corner, Section 36, T7N R12W, and City survey records.

L.C.R.C. #4127

N face 8" steel light pole S 10° W 22.58' E face 12" steel guy pole S 80° W 88.63' S 1/4 cor. Sec. 36, 7-12 N 90° W 34.14' P.A. 345 1990 KENT COUNTY

PEER APPROVED

CHAIRMAN

The selected location is accepted by me and is generally accepted by professional surveyors as the bestavailable evidence of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - L-1 Standard Kent County Monument

N face fiberglass light pole N 79° E 26.70°

N face 8" steel light pole S 10° W 22.58'

E face 12" steel guy pole S 80° W 88.63

S 1/4 cor. Sec. 36, T7N R12W, N 90° W 35.14°

RANDY J.
KOLEHOUSE
LAND
SURVEYOR
NO.
25854

Signed by Marely Followerse
Surveyor's Michigan License No. 25854

11/21/94