SURVEY & REMONUMENTATION

Kent County Remonumentation

STATE OF MICHIGAE COUNTY OF KEST RECEIVED FOR RECORD

APR 2 8 1995

LAND CORNER RECORDATION CERTIFICATE 91, NOV 29 AH 9: 25

COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

1	Kent		In: Corner C	ا منت ا	build and	
*	(County)	Located	in. Comer C	,00e - <i>1-1</i>	REG. OF DEEDS	
, Pu	ablic Land Survey	T T	R 12W M-3 RRR			
. Pr	operty Controllin	g . ST_	_ R		B € U O.	
in	Section	s T	_ R		7503	
	scellaneous operty in Sec.	S T S T			Register of Deeds Stamp & File N	umber
. Lo	t No	_ , Recorded Plat				J K I M
						<u> </u>
			•		2 6 5 4 3	
					3	
F	Randy Kolehouse	in a field survey (on July 15	19 94	5 1 1 1 1 1 1	-1112
o here Lines	eby certify that under 1 and 2 above we	er requirements of P.A. 74, are in conformance with	Michigan P.A. of 1970, the corregulations and rules therefor States Department of the Inte	ner points mentioned re as required in the	18-17-16-1-15-1	-1413
oove v	vere in conformanc of Law; establishe	e with the rules of the Mid	that the corner points mention thigan Board of Land Surveyor umented, re-monumented, re-	rs or by a Decree of a	9	-23-1-24
•	sed below:				10 -30 -29 -28 -27	-2625
OTE:	Not more than on this certific		ame town and range, may	be recorded	12 31 32 33 34	-3536
De	escription of origi	nal monument and acc	essories and/or subseque	ent restoration:	P.A. 345 1990 KENT COUNTY	,
. 50			I lives	Set Post	PEER APPROVED/8/11/9	
	1831	G.L.O. Notes	L. Lyon Williams & Works		<u> </u>	77
	1910-1950	Survey Records	Williams & Works	City Iron	CHAIRMAN True	Lupes
м-з			-	City Iron City Iron	<u> </u>	Tuper

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - М-3 Found K.C. Monument in C/L of Division Avenue N-S and Burton Stret E-W per L.C.R.C.'s #3901 and #4717 as set by William Byl in place of a City Iron he found in a monument box which checked Williams & Works and City City of Grand Rapids survey records.

L.C.R.C. #4717

Marble face of bldg. corner N 50° W 52.30' NE corner of fndn. of bank bldg. S 53° W 50.08' "X"-conc. base of sign pole N 50° E 54.26' K.C. mon. (NW cor. Sec. 7, 6-11) S 00° W 19.84' L.C.R.C. #3901

Marble face of bldg. corner N 50° W 52.30' K.C. mon. (NW cor. Sec. 7, 6-11) S 00° W 19.84'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Standard Kent County Monument Marble face of bldg, corner N 50° W 52,30' NE corner of fndn. of bank bldg. S 53° W 50.08' "X"-conc. base of sign pole N 50° E 54.26' "X"-conc. base S 25° E 84.90" Kent County Monument (NW cor. Sec. 7, 6-11) S 00° W 19.84'

RANDY J. KOLEHOUSE SURVEYOR SED LAND SUP

Signed by Kandy	I Kole Jeans
Surveyor's Michigan License No	/ /