## SURVEY & REMONUMENTATION



1995

MAR 0 3 1998

## LAND CORNER RECORDATION CERTIFICATE CECTION t 74, Mich. P.A. 1970

	SECTION	Filing Requirement of Ac
For corners in		KENT COUNTY REM

NUMENTATION

. 0, 0	OTTION IN		112.11 00		577	1	$\neg 1/Z$		7770	2,1	1 111	
<del></del>	Kent (Coun	ty)	Located in: Vergennes Township	Corner Code #		1		7 .:	်း မှာ	TON THE		
1.	Public Land	Šurvey	T <u>7N</u> R <u>9W</u> T R T R	A-7		10	۶ 289		8	Õ		
	Property Cor in Section	ntrolling S_	TR TR		Registe		eds Sta		File N	umbo	∍r	
	Miscellaneou Property in S	s s_ Sec. s_	TR TR									
					<u> </u>				i			
l, do he in lin curre Mans abov Cour	Randy Kole ereby certify these of and 2 a ent manual of agement or by e were in con t of Law; essed below: E: Not mo	house , in hat under requirement of the confusion of the	ents of P.A. 74 Michigan P.A ormance with regulations at of the United States Depar t of Law and/or that the corn ules of the Michigan Board o	ly 15, 1997 19	nentioned  ed in the  of Land  4 and 5  cree of a	7 - 18 - 19 - 30 - 30 19	- 17 17 29 23 23 23 23	F G	H	11	1	113-113-113-113-113-113-113-113-113-113
A.	Descriptio	n of original mon	ument and accessories a	ınd/or subsequent restora	ation:	-31-	32	-33	_34 	35	士;	36-
A-7	1956 1975 1977 1981	G.L.O. Notes Witness Map L.C.R.C. #800 L.C.R.C. #974 L.C.R.C. #1918	Mullett K.C. Surveyor Moore & Bruggink Exxel Engineering Jonker Land Surveys Exxel Engineering	Set Post Iron Iron (M-7, T7N, R10W) 1/2" Iron Fnd. 3/4" Rd. Iron / Set I K.C. Monument	CHAIRN	APPRO	VED 4	9/21 N	9/9/ DL	1	hei	L

Note: This corner is common with M-7, T7N, R10W.

L.C.R.C. #8052

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Rob Jonker on 7/14/81 and was recorded per L.C.R.C. #1918.

K.C. Monument (M-7, T7N, R10W)

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Glaza & Associates

Found a Standard Kent County Monument at the fence post on the corner of a fence line running North and East per L.C.R.C.'s #1918, #5823 and #8052 as set by Rob Jonker in place of a 3/4" round iron he found which checked L.C.R.C.'s #974, #800 and the K.C. Surveyor's records.

L.C.R.C. #1918

Remon. tag on S side 8" Oak N 66° E 8.98' Remon, tag on E side 14" Oak S 14° E 12.47' Remon. tag on W side 15" Oak N 07° E 18.46' Remon. tag on S side 9" W. Ch. S 47° W 33.97' Remon. tag on SW side 10" Tw. W. Ch. N 33° W 25.95' L.C.R.C. #8052

Nail & K.C. remon tag in S side 10" Oak N 71° E 9.09' Nail & K.C. remon tag in E side 18" Oak S 15° W 12.78' Nail & K.C. remon, tag in W side 18" Oak N 02° E 18.42' Nail & K.C. remon tag in SW side 14" Twin W. Cherry N 34° W 25.90' Nail & K.C. remon tag in S sie 9" W. Cherry (dead) S 44° W 33.87'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- A-7 Standard Kent County Monument

Nail & K.C. remon. tag on S side 10" Oak N 71° E 9.09'

Nail & K.C. remon. tag on E side 18" Oak S 15° W 12.78'

Nail & K.C. remon, tag on W side 18" Oak N 02° E 18.92'

Nail & K.C. remon. tag on SW side 16" Twin Cherry N 34° W 25.90'

Signed by

KOLFHOUSE LAND No. SED LAND S

Surveyor's Michigan License No.

25854