



MAR 08 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			KENT COUNTY REMONUMENTATION						유	·				
1	Kent (County)		Located ir	1: Vergennes Township	Cor	ner Code #			F DEEDS		H			: : :*
1. [Public Land Survey		T	R R		D-12			S(\$	d: 0 0	3 5	9	*
	Property Controlling		_ T	R					 .a. a	3 A C				
	n Section Viscellaneous								I.	993	0			
	Property in Sec.						Reg	gister	of Dec	eds Sta	mp &	File N	dumb	er
	Lot No													
	Private Claims			· · · · · · · · · · · · · · · · · · ·				A	ВС	D E	F G	н —	l J	K
	,							3	-6	-5-		_3_	2-	
I, <u>Randy Kolehouse</u> , in a field survey on <u>January 6</u> 19 <u>98</u> , do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered,							4	-18	1720	16	15	14-		
	d as expressed below:							9	++			_		+
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.								10	30	29	28	27	26-	$\frac{1}{1}$
A. Description of original monument and accessories and/or subsequent restoration:									31	•	33	34 	- 3 5-	+
D-12	: This corner was no	•				•		13						
		s Map C. #1169		. Surveyor iams & Works	ŧ	Concrete Monum "T" Iron	nent P.A. 34	E 10	90 KI	=NT (<i>AU</i> OC	IJŢΥ		
							P.A. 34	J IJ			/	10	\boldsymbol{a}	

B Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-12 Found a "T" iron 2.0' North of the C/L of Bennett Street (gravel) running East and West on line of a tree row running North and South per L.C.R.C. # 1169. Iron is 0.2' West of the intersection of 1/4 lines. Accepted iron as Center of Section.

K.C. Witness Map

L.C.R.C. #1169

24" Oak South 31.85' (m. 30.83')

18" Oak N.40°W. - 46.05' (m. 46.00') 16" Oak N.25°W. - 26.90' (m. 26.84') 36" Oak South - 30.80' (m. 30.83') 14" Hickory N.60° E. - 57.75' (m. 57.77')

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-12 Replaced "T" Iron with a Standard Kent County Monument

Nail & K.C. remon" tag on SW side 18" Oak N 40° W 46.00' Nail & K.C. remon. tag on NE side 16" Oak N 25° W 26.84' Nail & K.C. remon. tag on W side 36" Oak South 30.83' Nail & K.C. remon. tag on SE side 14" Hickory N 60° E 57.77" Nail & K.C. remon. tag on SE side 14" Oak N 81° E 65.50' C/L of gravel road running E-W, South 2.0'

On tree row running N-S

25854 Surveyor's Michigan License No.

> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

RANDY J.

KOLEHOUSE