

EAR 0 8 1399 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

\$7.00			LENG 보호 급명을 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 \			
For c	orners in		KENT COUNTY REM		1	STAT COU RECEN
	Kent	SECTION Located	in: Vergennes Corner		REG.	1 2 BES
	(County)		Township		9 /	
1. F	Public Land Su		R_9WF-	6	哥人	
1.31			_ R		S S	6 8 8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
			RR		<i>"</i>	· 8 *
2. F	Property Contro	olling S T	. R			
	n Section	S T	_ R		10939	}
	Aiscellaneous Property in Sec	S T c.	_ R		Register of Deeds Sta	ımp & File Number
•	Topolty III occ	,. 01	_ n			
4. L	.ot No	, Recorded Plat				
5. F	Private Claims				— авс D Е	F G H I J K L
	ř.				2	
	•				3	
		use, in a field surve				9 10 11 12-12-
		nat under requirements of P and 2 above were in conforma				
in the	current manua	al of survey instructions of the	United States Department	of the interior, Bureau of	f 6 1B 17-	15 14 13
		r by a decree of a Court of Late in conformance with the rule:				
		of Law; established, re-esta				-21222324-
	as expressed	below:			9	
NOTE		than 4 corners, all in the s	same town and range, ma	ay be recorded	10	28 27 26 25
	on this c	ertificate.			11	
A.	Description	of original monument and a	ccessories and/or subse	equent restoration:	12 31 32	-33-34-35-36-
F-6	This corner was not originally set by the G.L.O.					
-	1937 Witness Map K.C. Surveyor			2" Iron	P.A. 345 1990 K	ENT COUNTY
		L.C.R.C. #399	Williams & Works	X Cut on Rock	PEER APPROVE	D 10/22/198
	1994	Cert. Survey L. 263 P. 47	Exxel Engineering	Iron Stake	CHAIRMAN	my fuher
					ν.	/
B.	Description	of corner evidence found a	nd/or method applied in	restoring or reestablisl	hing corner:	
F-6	Did not find 8" stone shown in L.C.R.C. #399. Set a point using witnesses from Cert. Survey L. 263 P. 47 and L.C.R.C. #399. This point is 2.6' East and 0.3' North of the intersection of 1/4 lines. Accepted as Center of Section.					
	•					
	Cer	t. Survey L. 263 P. 47		L.C.R.C. #399	9	
		lail in NE sde 15" Walnut S 60° W 10.12').51'	
·		ail in Wisde 8" Ash N 10° E 1				
-		ail in S sde 20" Walnut East (ail in N sde 26" Walnut West		20" Walnut S70°	₾ 63.89	
				M		
:		I location is accepted by me on of the original corner.	and is generally accepted	d by professional survey	yors as the best availa	able evidence
C.	Description	of monument for corner an	d accessories establishe	ed to perpetuate locatin	na the position of the	corner:
F-6		ard Kent County Monument			3	
	Nail & K.C. remon. tag on S side 18" Walnut S 60° W 10.20'			July OF	MICA:	
	Nail & K.C. remon. tag on W side 10" Ash S 20° E 31.43'				HALE.	Qq.
	Nail & K.C. remon. tag on N side 26" Walnut West 20.39' Nail & K.C. remon. tag on W side 10" Ash N 00° E 12.87'				RAND)Y J.
_		K.C. remon, tag on N side 8"				ND 🛊
•	'. Dbl. he	aded nail on S side 20" Wal	nut East 66.88'			EYOR .
		fence line running E-W, Nor	th 25' ±		25	854
	rence	line running N-S, East 40' ±	•		SED I AL	NO SURVEY.
0:	when he	mile QV	Chin	Det 11/	18/90	1年 中国 - T 2度 中国 P ^G 東京
Signe	au by	A PARTITION		Date//	0/16	

25854

Surveyor's Michigan License No.