

Property in Sec.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 KENT COUNTY REMONUMENTATION

- SECTION

Kent	Loc	cated in: Vergennes	Corner Code #		
(County)		Township			
1. Public Land Survey	т	<u>7N</u> R <u>9W</u>	M-3		
· .	Т	R			
	Т	R			
	т	R			
2. Property Controlling	s T	R			
in Section	s т	R			
3. Miscellaneous	s T	В			

10949 Register of Deeds Stamp & File Number

i, :: Lot No,	Recorded Plat
. Private Claims	

in a field survey on September 8 Randy Kolehouse do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: Α.

William Byl

M-3 1837 G.L.O. Notes 1877 Notes 1990 L.C.R.C, #5313 1995 L.C.R.C. #8277 N. Brookfield Ionia Co. Witness Book

T. Chettleburgh

Set Post N/A

K.C. Monument

Fnd. Stones in Ring / Set K.C. Mon. in Center of Stones P.A. 345 1990 KENT COUNTY

PEER APPROVED

Note: This corner is common with A-3, T7N, R8W.

CHAIRMAN This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by T. Chettleburgh on 2/5/90 and was recorded per L.C.R.C. #5313.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a Standard Kent County Monument in woods per L.C.R.C.'s #5313 and #8277 as set by T. Chettleburgh in the center of stones he found which checked notes from the Ionia County witness book. No occupation lines were visible.

L.C.R.C. #5313

Nail & KC Remon tag in SE side of 20" B. Oak N 19° E 16.13' Nail & KC Remon tag in N. side of 18" B. Oak S 89° E 40.92' Nail & KC Remon tag in NE side of 12" Oak S 49° E 26.98' Nail & KC Remon tag in SE side of 12" W. Oak S 23° W 24.15' Nail & KC Remon tag in NW side of 14" W. Oak S 56° W 10.71' 10.711)

Nail & KC Remon tag in NE side of 15" W. Oak N 68° W 12.44'

L.C.R.C. #8277

11

Nail & KC Remon. tag SE side of 22" B. Oak N 19° E 16.13' (m. 16.13') Nail & KC Remon. tag N. side of 20" B. Oak S 89° E 40.92' (m. 40.94') Nail & KC Remon. tag NE side of 14" Oak S 49° E 26.98' (m. 27.00') Nail & KC Remon. tag, SE side of 14" W. Oak S 23° W 24.15' (m. 24.16') Nail & KC Remon, tag NW side of 14" W. Oak S 56° W 10.71'-(m.

Nail & KC Remon. tag NE side of 15" W. Oak N 68° W 12.44' (m. 12.46')

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

Standard Kent County Monument

Nall & K.C. remon. tag on SE side of 22" B. Oak N 20° E 16.13' Nail & K.C. remon. tag on N. side of 20" B. Oak S 88° E 40.94'

Nail & K.C. remon. tag on NE side of 14" Oak S 51° E 27.00'

Nail & K.C. remon. tag on SE side of 14" W. Oak S 25° W 24.16'

Nail & K.C. remon. tag on NW side of 14" W. Oak S 60° W 10.71'

Nail & K.C. remon, tag on NE side of 15" W. Oak N 65° W 12.46'

Signed by EKRTH TECH

Date

RANDY J. **KOLEHOUSE** LAND

25854

Surveyor's Michigan License No. 25854