MAR 0 S 1999

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 SECTION For corners in KENT COUNTY REMONUMENTATION Located in: Vergennes Kent Corner Code # (County) Township **Public Land Survey** <u>7N R 9W</u> **Property Controlling** in Section 10823 Miscellaneous Register of Deeds Stamp & File Number Property in Sec. . Recorded Plat Private Claims Randy Kolehouse _, in a field survey on _ January 9 do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of 6 Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: Not more than 4 corners, all in the same town and range, may be recorded 10 on this certificate. 11 12 Description of original monument and accessories and/or subsequent restoration: M-9 1837 G.L.O. Notes N. Brookfield Set Post 1973 L.C.R.C. #538 Williams & Works Iron at Stone 1981 L.C.R.C. #1999 Fnd. "T" Iron / Set K.C. MonumentP.A. 345 1990 KENT COUNTY Jonker Land Survey CHAIRMAN June 18/18 1995 L.C.R.C. #8283 William Byl K.C. Monument Note: This corner is common with A-9, T7N, R8W. This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Rob Jonkel on 8/11/81 and was recorded per L.C.R.C. #1999. Description of corner evidence found and/or method applied in restoring or reestablishing corner: B. Found a Standard Kent County Monument 170' ± East of the C/L of Montcalm Avenue (gravel) running South and Northwesterly, on top of steep hill, on line of a tree row running Easterly per L.C.R.C.'s #1999 and #8283 as set by Rob Jonker in place of a "T" iron he found by a stone which checked L.C.R.C. #538. L.C.R.C. #1999 L.C.R.C. #8283 Remon. tag on NW side 10" Walnut N32°E 11.13' Nail & KC Remon. tag NW side 10" Walnut (dead) N32°E 11.21' (m. 11.13') Remon. tag on N side 15" Tr/Oak S80°E 36.25' Nail & KC Remon. tag N. side 18" Tri. Oak S80°E 36.10' (m. 36.08') Remon, tag on W side 10" Tr. Oak S02°E 18.52' Nail & KC Remon. tag W. side 14" Tri. Oak S02°E 19.05' Remon. tag on SW side 10" Tw. Oak N50°W 28.24' Nail & KC Remon. tag SW side 14" Tw. Oak N50°W 28.10' (m. 28.05') Nail & KC Remon. tag W. side 24" Tw. Oak N15°E 33.08' (m. 33.19') The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C. E OF MICHIGA M-9 Standard Kent County Mönument Nail & K.C. remon. tag on NW side 10" dead Walnut N 32° E 11.13' RANDY J. Nail & K.C. remon. tag on N side 18" Tri. Oak S 80° E 36.08' **KOLEHOUSE**

25854 CAND SURVE C/L of gravel road running South and Northwesterly, West 170' + Signed by EASTH TECH Surveyor's Michigan License No.

Nail & K.C. remon. tag on W side 14" Tri. Oak S 02° E 19.05"

On line of tree row running East

Nail & K.C. remon. tag on SW side 14" Twin Oak N 50° W 28.05' Nail & K.C. remon. tag on W side 28" Twin Oak N 15° E 33.19'

LAND

No.