

MAR 08 1999 .

, Recorded Plat

SECTION For corners in		LAND CORNER RECORDATION CERTIFICATION Filing Requirement of Act 74, Mich. P.A. 19 KENT COUNTY REMONUMENTATION) (38 E	
	Kent (County)		Located in:	Vergennes Township	Corner Code #	6. OF	လ က
1.	Public Land Survey		T	R	M-10	DEEDS	計 9:58
2. 3.	Property Controlling in Section Miscellaneous Property in Sec.	s	T T T	R R		10824 Register of Deeds Stamp	& File

Number

I, Randy Kolehouse, in a field survey on	January 8	1998,					
do hereby certify that under requirements of P.A. 74 M							
mentioned in lines 1 and 2 above were in conformance with	regulations and rules there	fore as required					
in the current manual of survey instructions of the United S	tates Department of the inte	erior, Bureau of					
Land Management or by a decree of a Court of Law and/or							
4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a							
Decree of a Court of Law; established, re-established,							
found as expressed below:							

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

M-10 1837 G.L.O. Notes 1977 L.C.R.C. #1062 1981 L.C.R.C. #2000 1995 L.C.R.C. #8284

В.

Private Claims _

N. Brookfield Williams & Works Set Post

K.C. Monument

Iron in Monument Box

Jonker Land Survey William Byl

Fnd. Boat Spike / Set K.C. Monument in Mon. Box

10

13

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by

P.A. 345 1990 KENT COUNTY

PEER APPROVED 19 198

Note: This corner is common with A-10, T7N, R8W.

spike he found in a monument box which checked L.C.R.C. #1062.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found a Standard Kent County Monument at the C/L intersection of Flat River Drive (bit.) running East and West and Montcalm Avenue (bit.) running North and South per L.C.R.C.'s #2000 and #8284 as set by Rob Jonker in place of a boat

L.C.R.C. #2000

8/11/81 and was recorded per L.C.R.C. #2000.

L.C.R.C. #8284

Remon. tag on NW side 36" Oak N50°E 49.40' Remon. tag on S side 14" Oak N76°W 102.38' C/L B.T. South 1.5'

Nail & KC Remon. tag NW side 42" Oak N50°E 49.28'

Nail & KC Remon, tag W. side 42" Oak \$30°E 56.40' (m. 56.27')

Nail & KC Remon. tag E. side 18" Oak S20°W 112.15' (m. 112.23')

Nail & KC Remon, tag NW side 14" Pine S70°W 118.40'

Nail & KC Remon. tag E. side 28" Oak N20°W 81.22' (m. 81.27')

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

of the position of the original corner.

Description of monument for corner and accessories established to perpetuate localing the position of the corner:

M-10 Standard Kent County Monument

Nail & K.C. remon. tag on NW side 42" Oak N 50° E 49.28'

Nail & K.C. remon. tag on W side 42" Oak S 30° E 56.27' Nail & K.C. remon. tag on E side 18" Oak S 20° W 112.23'

Nail & K.C. remon. tag on NW side 14" Pine S 70° W 118.40' Nail & K.C. remon. tag on E side 28" Oak N 20° W 81.27'

On C/L "X" of bit. roads running N-S & E-W

Signed by EARTH TECH

RANDY J. KOLEHOUSE LAND No. 25854 LAND SURVEY 25854

Surveyor's Michigan License No. 25854