For corners in

SURVEY & REMONUMENTATION

MAR 0 3 1998

S	Fſ	T	10	N
O			11	IV

LAN Fillir

ng Require	R RECORDATION CERTIF ment of Act 74, Mich. P.A UNTY REMONUMENTATION	1970 A STA	
Ada Township	Corner Code #	AM 8: 5	
R <u>10W</u> R R	F-5		
R R R		10198	
• • ——		Parinter of Deada Stomp 9 Ella Number	

	(County)	Located in: Ada Corner Code # Township	8. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5.
1.	Public Land Survey	TR	
•	Dominio O South	T R	4040-
2.	Property Controlling in Section	S T R S T R	10198
3.		STRSTR	Register of Deeds Stamp & File Number
4. 5.		, Recorded Plat	A B C D E F G H I J K L
			2
ι.	Randy Kolehouse	. in a field survey on April 1 19	97

do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

P.A. 345 1990 KENT COUNT F-5 1831 G.I.O. Notes Mullett Set Post PEER APPROYED 5/22 1962 Witness Map K.C. Surveyor 3/4" Iron 1974 L.C.R.C. #1086 Medema, Van Kooten & Assoc. Pinched Iron CHAIRMAN Fnd. 1" Pinched Iron / Set K.C. 1982 L.C.R.C. #3149 Moore & Bruggink 1989 LCRC #5138 T. Chettleburgh K.C. Monument

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Moore & Bruggink on 6/21/82 and was recorded per L,C.R.C. #3149.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-5 Found a damaged Standard Kent County Monument 2.4' South of the C/L of 2 Mile Road (gravel). Reset point per witnesses from L.C.R.C.'s #3149 and #5138 as set in 1982 by Moore & Bruggink per L.C.R.C. #1086 and the Kent County suvey records.

L.C.R.C. #3149

L.C.R.C. #5138

K.C. Nail & Cap 24" Hickory South 45.96'

K.C. Nail & Cap 10" Double Ash S 70° W 68.18'

K.C. Nail & Cap 5" Hickory N 60° W 63,61'

- K.C. Remon. Tag & Nail NW side Tri. 8" Oak N 47° E 44,23' (m. 44,67')
- K.C. Remon. Tag & Nail SW side 13" Hickory S 52° E 26,60' (m. 26.91')
- K.C. Remon. Tag & Nail NE side 14" Hickory S 52° E 48.58' (m. 48.91')
- K.C. Remon. Tag & Nail East side 21" Hickory S 01° W 45.91' (m. 45.80')
- K.C. Remon. Tag & Nail North side Tw. 11" Ash S 70° W 68.10' (m. 67.65')

K.C. Remon. Tag & Nail South side 6" Hickory N 59° W 63.53' (m. 63.22')

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Date

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner; SANTE OF MICAYO

F-5 Reset a Standard Kent County Monument

Nail & K.C. remon, tag on NW side Triple 8" Oak N 47° E 44.23'

Nail & K.C. remon. tag on SW side 14" Hickory S 52° E 26.60'

Nail & K.C. remon. tag on NE side 14" Hickory S 52° E 48.58'

Nail & K.C. remon. tag on E side 22" Hickory S 01° W 45.91'

Nail & K.C. remon, tag on N side Twin 12" Ash S 70° W 68.10'

Nail & K.C. remon. tag on S side 6" Hickory N 59° W 63.53'

Signed by

CAND SURIE

Surveyor's Michigan License No.

25854

KOLEHOUSE

LAND

No.

25854