

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in KENT COUNTY REMONUMENTATION **SECTION** Located in: Ada Corner Code # (County) Township Public Land Survey 7N R_10W **Property Controlling** 10313 in Section Miscellaneous Register of Deeds Stamp & File Number Property in Sec. Lot No. , Recorded Plat Private Claims Randy Kolehouse , in a field survey on August 5 do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: G-11 1831 G.L.O. Notes Mullett Set Post K.C. Surveyor N/A Witness Map Iron & Stone 1971 L.C.R.C. #19 J. Spencer "T" Iron 1974 L.C.R.C. #736 W. Smith "T" Iron 1982 L.C.R.C. #2713 Williams & Works "T" Iron (to correct L.C.R.C. #386 recorded 4/3/72) 1981 L.C.R.C, #2586 Jonker Land Survey Fnd. "T" Iron / Set K.C. Monument 1989 L.C.R.C. #5151 T. Chettleburgh K.C. Monument This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Rob Jonker on 12/28/81 and was recorded per L.C.R.C. #2586. В. Description of corner evidence found and/or method applied in restoring or reestablishing corner: G-11 Found a Standard Kent County Monument 55' North of the C/L of Headley Street running East and West and 18' West of the West face of a brick building per L.C.R.C.'s #2586 and #5151 as set by Rob Jonker in place of a "T" iron he found at grade over a large stone 29" below grade which checked L.C.R.C.'s #2713, #736, #19, and the K.C. Surveyor's records. L.C.R.C. #2586 L.C.R.C. #5151 SW corner bldg. fnd. S43°E 24.78' Northwest corner building (corner brick) N 08° E 104.87' (m. 104.9') Perpendicular face of brick bldg. S88°E m/l 18.04' Perpendicular face of brick building S 86° E 18.06' SE corner bldg. fnd. N74°W 129.57' Southwest corner building foundation S 40° E 24.76' C/L top Hyd. #130 S57°W 58.91' K.C. Remon. Tag & Nail West side 18" Maple S 05° E 108.17' (m. 108.23') Centerline top Hydrant #130 S 60° W 58.90' (m. 59.0') Southeast corner buildling foundation N 71° W 129,47' (m. 129,58') The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. Description of monument for corner and accessories established to perpetuate locating the position of the corner

G-11 Standard Kent County Monument

NW cor. brick bldg. at foundation N 17° E 104.9'

SW cor. brick bldg. S 39° E 24.76'

Nail & K.C. remon. tag on W side 28" Maple S 03° E 108.23'

C/L top hydrant (behind Tri. Box Elder) S 61° W 59.0'

SE cor. bldg. foundation N 70° W 129.58'

Signed by_

25854 ENSED LAND

RANDY J.

KOLEHOUSE

CHEVEYOR

Surveyor's Michigan License No.

P.A. 345 1990 KENT COUNT

PEER APPROVED