REMONUMENTATION

\$7.00	
W.V.00	

MAR 0 3 1998

LAND CORNER RECORDATION CERTIFICATE

\$2.00 For corners in	SECTION	Filing Requirement	CORDATION CERTIF t of Act 74, Mich. P.A REMONUMENTATION	. 1970	an de	E/	97 DEC I	200 N	
Kent (County	/)	Located in: Ada Co Township	orner Code #		유민	CAN	5		
Public Land S	uįvey	T R T R	L-8		SCE		10:42		
2. Property Cont in Section 3. Miscellaneous	s	T R _T R	·		10	377			
Property in Se		Τ R Τ R	- T	Regi	ister of De	eds Stam	p & File	e Numb	er ·
Lot No	. Recorded	Plat							
. Private Claims	3	`	!		A B C	D = 1	: o .		<i>.</i> .
						1 1	G F		-
			1	166.14	2 6	-5	j ģ		
Bandy Koleh	ouee in a fi	ield survey onJanuary :	20 40 6	. =	3		_		
lo hereby certify that	at under requirements	of P.A. 74 Michigan P.A. of 197	30199 70. the comer points mer	otioned	4 - 7 - +	- k k	/——• 	0	12-
n lines 1 and 2 ab	ove were in conform	ance with regulations and rule	s therefore as required	in the	5	+++			++
surrent manual of s Management or by a	urvey instructions of decree of a Court of	the United States Department (Law and/or that the corner point	of the interior, Bureau of	f Land	6 18	-171	3	514-	13
bove were in confo	rmance with the rules	of the Michigan Board of Land	Surveyors or by a Decre	ee of a	7				
Court of Law; e expressed below:	stablished, re-establi	ished, monumented, re-monum	nented, recovered, four	nd as	819	20-20		2——23-	
in the second second	a than 4 aarmara al	1 le the court town out			9				+
on this	e man 4 corners, ar certificate.	I in the same town and range	a, may be recorded		10 30	29 2	327	726-	25-
									++
N. Description	of original monum	ent and accessories and/or	subsequent restoration	n:	12 31	-923	34	35-	30
-8 This corner	was not originally se	et by the G.L.O.			13 []				
1972	Witness Map L.C.R.C. #348	K.C. Surveyor Williams & Works	Iron 3/4" Iron in Monum	ent Box					
1975	L.C.R.C. #800	Moore & Bruggink	Monument Box	P.A. 345	1990 K	ENT CO	(TMU	107	
				PEER A	PPROVE	V 91	<u>25/</u>	<i>34</i> _	-/
				CHAIRM		nin	~J/	Lus	her
Description	of corner evidence	e found and/or method appli	ed in restoring or rees			/	/		
-8 Found a 3/4 Avenue (bit.	" pipe in a monume) running North and	nt box at the C/L intersection South per L.C.R.C.'s #348, # /4 lines. Accepted pipe as Ce	of Conservation Stree 800 and the K.C. Surve	t running E	East and V	Vest and is 10.9' \$	Mc Ca 3outh a	abe and	
K.C. Witnes	s Map - 1956	L.C,R.C. #348	ı		L.C.	.R.C. #80	0		
/ 16" @ak NE	54.71' (Face)	20" Oak N 55° E 5	5.72'	N	ail in 18" C	Dak NE 5	5.76'		
	,	Cor fe post N 45° \	N 45.65'		ail in cor. t			45.65'	
									·
The selected of the position	d location is accepte on of the original co	ed by me and is generally acco	epted by professional s	surveyors a	as the best	i availabl	e evide	∍nce	
Description	of monument for c	orner and accessories estal	olished to perpetuate	locating th	ne positior	of the o	omer:		
		dard Kent County Monument i				417,111	*******	··.	
	n 20" Oak N 55° E 5				Š	WIE OF	MIC	4/60	
	Cor. fence post N 4 K.C. remon. tag on	5° W 45.65' W side fence post N 40° W 4	6.43'		in the second	RA KOI	NDY J. EHOUSI	. <i>V</i>	. 4.1.1.1

Surveyor's Michigan License No.

Nail & K.C. remon. tag on W side Power pole N 25° E 82.08' Nail & K.C. remon. tag on SE side 22" Oak N 60*E 56.14' Nail & K.C. remon. tag on N side 10" Oak S 75° E 114.25'

25854

FORM APPROVED BY MICHGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1871 REVISED MAY 14, 1975 REVISED JAN., 1883

KOLEHOUSE