

Surveyor's Michigan License No.

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

	***				
NONU	MENTAT	ION			

Ford	APR 2 (		ng Requirement of	Act 74, Mich. P.A. 1970 MONUMENTATION	34 UEC -0	•	
	Kent COMM	IISSIONLocated in:	Corne	r Code #	Luigh	Road	
1.	Public Land Survey	T 7N	R_11W	D-11	REG. OF	DEEDS	**
••	, abio cana canto,	т т	_				
	Property Controlling	ST	R		1/4 1 M (		
	In Section S T R R Register of Deeds Stamp & File					umher	
	Property in Sec.	s t	R		egister of beeds		Aminei
	Lot No,						
<b>5.</b> 1	Private Claims				A B C D	E F G H I	
					3 6 5		- 2 -   - i -
do he in line curre. Mana above	ereby certify that under re es 1 and 2 above were nt manual of survey inst agement or by a decree of were in conformance wi	equirements of P.A. 74 M in conformance with re ructions of the United S f a Court of Law and/or the fifth the rules of the Michigan	lichigan P.A. of 1970, the gulations and rules the tates Department of the nat the corner points me gan Board of Land Sun	19 94 , ne corner points mentioned erefore as required in the le interior, Bureau of Land entioned in lines 3, 4 and 5 yeyors or by a Decree of a led, recovered, found as	4 7 6 5 18 17 7 8 19 20	10 15	
	ssed below:			•	10 20 29		
NOTE	E: Not more than 4 on this certificate	corners, all in the sam	e town and range, m	ay be recorded	11		
Α.	Description of original	al monument and acc	essories and/or sub	sequent restoration:	13 31 32	33 - 34	35 36-
D-11	N/A Sur 1984 L.C 1988 L.C	.O. Notes vey Records .R.C. #3774 .R.C. #4592	Mullett City of Grand Rapi William R. Byl Bueche	End DV 10ad	nt P.A. 345 19 PEER APP	rovez <i>///</i>	3/94
	on 2/16/84 and was re	ecorded per L.C.R.C. #	3774.	mentation Peer Group and	a monumented b	y William R. By	ı
В.	Description of corner	r evidence found and/	or method applied ir	restoring or reestablish	ing comer:	·	
D-11				nd Wealthy Street E-W pecks street improvements.		774 and #4592	
	L.C.R.C.	. #3774		L.C.R.C. #4	592		
	Face of street light po SW cor. 2'x2' concrete Nail & tag S side p. po Face of brick veneer,	-	E 46.43'	Face of hydrant (at wall Face of street light pole SW cor. 2'x2' concrete   Nail & tag S side p. pole Face of brick veneer, N at S side of entry	(at walk level) S post N 45° E 46. N 65° E 46.78' E cor. of bldg. #1	60° E 46.43' 13'	
	The selected location of the position of the co	is accepted by me and priginal corner.	is generally accepted	d by professional surveyor	s as the best av	ailable evidence	
C.	Description of monur	ment for corner and a	ccessories establish	ed to perpetuate locating	the position of	the corner:	
D-11	Face of street lig SW cor. 2'x2' cor Nail & K.C. remo	Monument (at walk level) N 55° W (at walk level) S ncrete post N 45° E 46 on. tag S side p. pole N neer, NE cor. of bldg. #	S 60° E 46.43' .13'   65° E 46.78'	ry S 40° W 50.44'	To the state of th	RANDY J. KOLEHOUSE LAND SURVEYOR No. 25854	Contraction of the second
Signe	d by Glans	ly & Kohl	ea-	Date	11/94		:

25854