SURVEY & REMONUMENTATION

APR 2 8 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGA COUNTY OF KENT RECEIVED FOR RECO	

94 DEC -6 AM 9: 01

For comers in	COMMISSION
For comers in	Carlotte Comment

on this certificate.

NOTE:

KENT COUNTY REMONUMENTATION

Tui	Rond
REG. OF	FDEEDS

Corner Code # Located in: (County) **Public Land Survey** T_7N__R_11W_ **Property Controlling** in Section Miscellaneous Property in Sec.

_, Recorded Plat

Register of Deeds Stamp & File Number

5.	Private Claims		
		1	

Randy Kolehouse · in a field survey on June 21 do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Not more than 4 corners, all in the same town and range, may be recorded

Description of original monument and accessories and/or subsequent restoration:

E-8	1831 1920-1957 1960 1961-1967	G.L.O. Notes Survey Notes Survey Notes Survey Notes	Mullett Williams & Works MDOT Williams & Works	Set Post Iron PEER APPROVED Iron CHAIRMAN Mon. Box Fnd. Iron in Mon. Box/Set K.C. Mon.
	1984	L.C.R.C. #3919	William R. Byl	Fnd. Iron in Mon. Box/Set K.C. Mon.
	1988	L.C.R.C. #4559	Bueche	K.C. Monument

This comer was originally approved by the Kent County Remonumentation Peer Group and monumented by William R. Byl on 8/14/84 and was recorded per L.C.R.C. #3919.

- В. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Found standard Kent County Monument in C/L of Ball Avenue running N-S per L.C.R.C.'s #3919 and #4559 as set by E-8 William R. Byl in place of a 1" iron in monument box which he found which checked Williams & Works and MDOT survey records.

L.C.R.C. #3919

L.C.R.C. #4559

Face of curb S 90° W 18.10' NW cor. of brick veneer bldg. #810 N 50° E 84.95' SW cor. of brick veneer bldg. #810 S 50° E 79.34'

Face of curb S 90° W 18.10' NW cor. of brick veneer bldg. #810 N 50° E 84,95' SW cor. of brick veneer bldg, #810 S 50° E 79.34' C/L bit. road - N & S -- Ball Avenue

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Date

- Description of monument for corner and accessories established to perpetuate locating the position of the corner
- E-8 Standard Kent County Monument

Face of curb S 90° W 18.10'

NW cor. of brick veneer bldg. #810 N 50° E 84.95'

SW cor. of brick veneer bldg. #810 S 50° E 79.34'

C/L Ball Avenue (bit.) road - N & S

RANDY J. KOLEHOUSE LAND ASED LAND SUR

Signed by Canly	I Voletane
Surveyor's Michigan License No.	25854