SURVEY & REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT

RECEIVED FOR RECORD

94 DEC -6 AM 9: 01

APR 2 8 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 KENT COUNTY REMONUMENTATION

	ر ل	2 ي	QS	mel
		(2	, — ,
R	EG.	0F	DEED	S

Located in: Corner Code # Kent (County) **Public Land Survey** T_7N__ R_11W_ R **Property Controlling** _ R_ in Section R Miscellaneous Property in Sec.

_, Recorded Plat

7801 Register of Deeds Stamp & File Number

in a field survey on Randy Kolehouse July 13 do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a established, re-established, monumented, re-monumented, recovered, found as Court of Law: expressed below:

NOTE:

Private Claims

For corners in

Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

P.A. 345 1990 KENT COUN E-13 1831 G.L.O. Notes L. Lyon Set Post PEER APPROVED/11/3/94 1920 Survey Notes Williams & Works City Iron 1929 Survey Notes City of Grand Rapids City Iron 1985 L.C.R.C. #4236 William R. Byl Fnd. City Iron/Set K.C. Mon. 1988 L.C.R.C. #4589 Bueche K.C. Monument

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by William R. Byl on 1/10/85 and was recorded per L.C.R.C. #4236.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- E-13 Found standard Kent County Monument in the C/L of Hall Street running E-W 54.57' East of the NW corner Section 4 T6N R11W per L.C.R.C.'s #4236 and #4589 as set by William R. Byl in place of a City iron he found which checked Williams & Works and the City of Grand Rapids survey records.

L.C.R.C. #4236

L.C.R.C. #4589

NW cor. brick veneer hse, #1600 4' above grade S 25° W 81.74' SW cor. brick veneer hse. #1154 at grade N 35° W 72,39'

SW cor. brick retaining wall N 00° E 32.91' NE cor. (siding) hse. #1608 S 25° E 76.43' K.C. Monument N 90° W 54.58'

NW cor. brick veneer hse. #1600 4' above grade S 25° W 81.83' SW cor. brick veneer hae. #1154 at grade N 35° W 72.45'

SW cor. brick retaining wall N 00° E 32.91' NE cor. (slding) hse, #1608 S 25° E 76,43' K.C. Mon. NW cor. Sec. 4 T6N, R11W N 90° W 54.65'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original comer.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-13 Standard Kent County Monument

NW cor. brick veneer hse. #1600 4' above grade S 25° W 81.83'

SW cor. brick veneer hse. #1154 at grade N 35° W 72.45'

SW cor. brick retaining wall N 00° E 32.91'

NE cor. (siding) hse. #1608 S 25° E 76.43'

K.C. Mon. NW cor. Sec. 4 T6N, R11W N 90° W 54.65°

RANDY J. KOLEHOUSE SURVEYOR 25854 LAND SUR

Flakehouse Date Surveyor's Michigan License No.