## SURVEY & REMONUMENTATION





STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

APR 28 1995

For comers in

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

an OFC	-6	AM	9:	05
-	~ ~			

Kent (County)	Located in:	Corner Code #	REG. OF DEFINS	
Public Land Survey	T_7N_ R_11W T R T R	-11	HEG. OF BEEERS	
Property Controlling     in Section	S T R S T R		7824	
Miscellaneous     Property in Sec.	STR STR		Register of Deeds Stamp & File Number	
4. Lot No 5. Private Claims	Recorded Plat		2 6 5 4 9 2 1 X L	
do hereby certify that under re in lines 1 and 2 above were current manual of survey inst Management or by a decree of above were in conformance w Court of Law; established expressed below:	equirements of P.A. 74 Michigan P. in conformance with regulations ructions of the United States Dep if a Court of Law and/or that the cordith the rules of the Michigan Board, re-established, monumented, in	A. of 1970, the corner points mentione and rules therefore as required in the artment of the interior, Bureau of Lanner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of re-monumented, recovered, found a	9d 5   18   17   18   15   14   13   15   14   13   15   14   13   15   14   13   15   14   13   15   14   13   15   14   15   15   14   15   16   16   16   16   16   16   16	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.				

A. Description of original monument and accessories and/or subsequent restoration:

1984 Survey Records All Points Set Rebar 1985 L.C.R.C. #4245 William R. Byl Fnd. Rebar/Set K.C.Mon.	I-11	1985	L.C.R.C. #4245	William R. Byl	Find. Rebar/Set K. E. HADRMAN Francy Julie
---	------	------	----------------	----------------	--

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by William R. Byl on 1/15/85 and was recorded per L.C.R.C. #4245.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- I-11 Found standard Kent County Monument per L.C.R.C. #6386 as set by William R. Byl in place of a rebar he found which was set by all points, surveyors using Williams & Works, MDSH and Medema Van Kooten survey records.

L.C.R.C. #4245

L.C.R.C. #6386

No witnesses remain

C/L bottom of 2" gate post (0.5' above grd.) Southerly post N 16° E 147.32' C/L bottom of 2" gate post (0.5' above grd.) Northerly post S 57° W 40.51' Back of curb of west side of southbound lane East Beltline S 77° E 133.90' C/L bottom of end 2" fence post S 32° W 145.11'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original comer.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- I-11 Standard Kent County Monument

C/L bottom of 2" gate post (0.5' above grd.) Southerly post N 16° E 147.32' C/L bottom of 2" gate post (0.5' above grd.) Northerly post S 57° W 40.51' Back of curb of west side of southbound lane East Beltline S 77° E 133.90' C/L bottom of end 2" fence post S 32° W 145.11'

RANDY J.
KOLEHOUSE
LAND
SURVEYOR
NO.
25854
LAND SURV

Signed by Many	& Kolehouse
Surveyor's Michigan License No.	25854

12/1/94