SURVEY & REMONUMENTATION



APR 2 8 1995

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

	2	- 4			0.00	450		On C:	
-240	∕ ```	. 14	20.00	M		κ.	ריו	N. I	
			п г.				Ю	141	
	α,							1 13	

LAND CORNER RECORDATION CERTIFICATE DEC 16 AM 9: 24 Filing Requirement of Act 74, Mich. P.A. 1970

1. Public Land Survey T7N R 11N J-6 (Center, Sec 14) T R Sec 16 Tenses C. Glaza In a field survey on December 1 19 94 This section Recorded Plat Sec 16 Tense Sec 17 R Sec 16 Tense Sec 17 R Sec 17 R Sec 17 R Sec 17 R Sec 18 Tense S		Kent	_ Located In:	Corner Code ##	The wind	Gamey	
1. Public Land Survey T R Sec 14		(County)	;		חדת חל	needs	
## Sec 14) Fig. Fi	1 -	Dublic Land Survey	т7N _В 11W	J-6 (Center,	KEG. O	for his time to the	
T		:^^					
Property Controlling S T F F F F F F F F F		•					
A Sociol S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Register of Deed							
Miscellaneous S T R	2.	Property Controlling			t _s i	007	
Property in Sec. S T R		4			3	♥ 0 €.	
A Lot No. Recorded Plat 5. Private Claims 1. James C. Glaza in a field survey on December 1 19 94 1. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 1, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or tya Decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or tya Decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or tya Decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or tya Decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or tya Decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of the One	3.				Register of Dee	ds Stamp & File N	lumber
James C. Glaza in a field survey on December 1 19 94 do hereby certify that under requirements of P.A.74. Michigan P.A. of 1970, the corner points mentioned in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/of that the corner points mentioned in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/of that the corner points mentioned in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law, and of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law, and of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law, and of the United States Department of the Interior, Bureau of Land Management or States Department of the Interior, Bureau of Land Management or States Department of the Interior, Bureau of Land Management or States Department of the Interior, Bureau of Land Management or States Department of the Interior, Bureau of Land Management or States Department of Lan		Property in Sec.	S T R				
James C. Glaza in a field survey on December 1 19 94 do hereby certify that under requirements of P.A.74. Michigan P.A. of 1970, the corner points mentioned in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/of that the corner points mentioned in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/of that the corner points mentioned in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law, and of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law, and of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law, and of the United States Department of the Interior, Bureau of Land Management or States Department of the Interior, Bureau of Land Management or States Department of the Interior, Bureau of Land Management or States Department of the Interior, Bureau of Land Management or States Department of the Interior, Bureau of Land Management or States Department of Lan	3.1	Lat Na	acedad Plat	and the state of t			
do hereby certify that under requirements of PA 74. Michigan PA of 1970, the corner points mentioned in tines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of by a decree of a Court of Law and/or that the corner points mentioned in tines 3, 4 and 5 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with regulations and rules therefore as required in the current manual forms and the corner of the Michigan Board of Land Surveys or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below. NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. J-6 This corner was not originally set by the G.L.O. 1929-1946 survey records Williams & Works leaded stone set "T" iron @ intersection of 1978 LCRC #1174 Merdzinski. "Tirr iron @ intersection of 1978 LCRC #1174 Merdzinski. "Tirr iron @ intersection of "T" iron % lines Kent Co. Mon. 8. Description of corner evidence lound and/or method applied in restoring or reestablishing corner. J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the ½ lines. The Kent Country Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N	77° - ''		Colueu Flat		A S C	DEFGHI	JKLM
do hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interier, Bureau of Lad Management of by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Bopatranet of the Interier, Bureau of Lad Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Bopatranet of the Interior, Bureau of Lad Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Bopatranet of the Interior, Bureau of Lad Management of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the Michigan Bopatranet of Law and/or that the covered found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Jef This corner was not originally set by the G.L.O. 1929-1946 survey records Williams & Works leaded stone set "T" iron @ intersection of 1978 LCRC #1174 Mercizinski "T" iron @ intersection of "T" iron % lines Kent Co. Mon. B. Description of corner swidence found and/or method applied in restoring or reestablishing corner. Jef Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Mercizinski. This monument is 0.2? South and 0.8' West of the intersection of the ½ lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14** Maple N85°E 16.73 16** Oak S45°W 33.15' 4** Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0°W & 1.5°N	(4.°	Fritale Ciamo		the state of the s	2 6	- 5 4	_2 _ _ _
James C. Glaza In a field survey or December 1 19 94	e de la companya de La companya de la co				3		
do hereby certify that under requirements of PA. 74. Michigan PA. of 1970, the comerpoints mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with regulations and rules therefore as required in the conformance with the rules of the Michigan Bosapariment of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Bosapariment of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Bosapariment of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with reputation of Law and/or interior provides of Law and as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J=6 This corner was not originally set by the G.L.O. 1929-1946 survey records Williams & Works set "T" irron @ intersection of 1978 LCRC #1174 Mercianski "T" irron @ intersection of 1978 LCRC #1174 Mercianski "T" irron @ intersection of 1978 LCRC #1174 by John A. Mercianski. This monument is 0.2' South and 0.8' West of the intersection of the ½ lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14 "Maple N5°E 16.73 16" Oak \$10°K 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating t					4 7	- 8 9 - 10-1	1112
In lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States beparament of the Interior, Bursu of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below. NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-6 This corner was not originally set by the G.L.O. 1929-1946 survey records Williams & Works 1965 survey records Williams & Works 1965 survey records Williams & Works 1994 survey records Glaza & Associates Kent Co. Mon. 8. Description of comer evidence found and/or method applied in restoring or reestablishing corner: J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the ½ lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak \$15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				, 13		 	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of vp a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below. NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-6 This corner was not orriginally set by the G.L.O. 1929-1946 survey records Williams & Works leaded stone 1965 survey records Williams & Works set "T" iron @ intersection of 1978 LCRC #1174 Merdzinski "T" iron @ intersection of 1978 LCRC #1174 Merdzinski "T" iron @ intersection of "T" iron & lines 1994 survey records Glaza & Associates Kent Co. Mon. B. Description of comer evidence found and/or method applied in restoring or reestablishing corner. J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the ½ lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14 " Maple N85"E 16.73 16" Oak S10"W 33.15' 4 " Basswood N15"W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.	do	hereby certify that under requi	rements of P.A. 74, Michigan P	A. of 1970, the corner points men	tioned 6 18	-171615	3-
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-6 This corner was not originally set by the G.L.O. 1929-1946 survey records Williams & Works leaded stone 1965 survey records Williams & Works set "I" irron @ intersection of 1978 LCRC #1174 Merdzinski "T" irron it lines 1994 survey records Glaza & Associates Kent Co. Mon. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2! South and 0.8! West of the intersection of the ½ lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0!W & 1.5!N	in l	lines 1 and 2 above were in C	conformance with regulations tions of the United States Der	and rules therefore as required artment of the Interior, Bureau o	fland 7		
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law, established, re-established, monumented, recovered, found as expressed below. NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-6 This corner was not originally set by the G.L.O. 1929-1946 survey records Williams & Works leaded stone 1965 survey records Williams & Works set "T" iron @ intersection of 1978 LCRC #1174 Merdzinski "T" iron intersection of 1978 survey records Glaza & Associates Kent Co. Mon. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the ½ lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45'W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	Ma	nagement or by a decree of a C	Court of Law and/or that the co	ner points mentioned in lines 3, 4	land5 8 19	-202122	2324-
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-6 This corner was not originally set by the G.L.O. 1929-1946 survey records Williams & Works leaded stone 1965 survey records Williams & Works set "T" iron @ intersection of 1978 LCRC #1174 Merdzinski "T" iron @ intersection of 1978 LCRC #1174 Merdzinski "T" iron it lines 1994 survey records Glaza & Associates Kent Co. Mon. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the image in the second of	abo	ove were in conformance with	the rules of the Michigan Boar	d of Land Surveyors or by a Decr	ee of a		
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-6 This corner was not originally set by the G.L.O. 1929-1946 survey records Williams & Works leaded stone 1965 survey records Williams & Works set "T" iron @ intersection of 1978 LCRC #1174 Merdzinski "T" iron % lines 1994 survey records Glaza & Associates Kent Co. Mon. 8. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the % lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.76' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:			established, monumented, r	e-monumented, recovered, tou	10 -30	2928 27	2625
A. Description of original monument and accessories and/or subsequent restoration: J-6 This corner was not originally set by the G.L.O. 1929-1946 survey records Williams & Works leaded stone 1965 survey records Williams & Works set "T" iron @ intersection of 1978 LCRC #1174 Merdzinski "T" iron it lines 1994 survey records Glaza & Associates Kent Co. Mon. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the it lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak \$10°W 10.78' 16" Oak \$45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	•		more all in the came town	and range may be recorded	11		
A. Description of original monument and accessories and/or subsequent restoration: J-6 This corner was not originally set by the G.L.O. 1929-1946 survey records Williams & Works leaded stone 1965 survey records Williams & Works set "T" iron @ intersection of 1978 LCRC #1174 Merdzinski "T" iron # lines 1994 survey records Glaza & Associates Kent Co. Mon. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the # lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	NC		iters, all lift the same town	and range, may be recorded		32 33 34	35 36
J-6 This corner was not originally set by the G.L.O. 1929-1946 survey records Williams & Works leaded stone 1965 survey records Williams & Works set "T" iron @ intersection of 1978 LCRC #1174 Mendzinski "T" iron & lines 1994 survey records Glaza & Associates Kent Co. Mon. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Mendzinski. This monument is 0.2' South and 0.8' West of the intersection of the & lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N		on this certificate.			~;		
J-6 This corner was not originally set by the G.L.O. 1929-1946 survey records Williams & Works leaded stone 1965 survey records Williams & Works set "T" iron @ intersection of 1978 LCRC #1174 Mendzinski "T" iron & lines 1994 survey records Glaza & Associates Kent Co. Mon. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Mendzinski. This monument is 0.2' South and 0.8' West of the intersection of the & lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N	Α.	Description of original me	onument and accessories	and/or subsequent restoratio	n;		
1929-1946 survey records Williams & Works leaded stone 1965 survey records Williams & Works set "T" iron @ intersection of 1978 LCRC #1174 Merdzinski "T" iron & intersection of 1994 survey records Glaza & Associates Kent Co. Mon. B. Description of comer evidence found and/or method applied in restoring or reestablishing corner. J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the & lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				•			
1965 Survey records Williams & Works set "T" iron @ intersection of 1978 LCRC #1174 Merdzinski """ iron & intersection of 1978 LCRC #1174 Merdzinski """ iron & lines 1994 Survey records Glaza & Associates Kent Co. Mon. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the & lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N			- -			han-	
1978 LCRC #1174 Merdzinski "T" iron ¼ lines 1994 survey records Glaza & Associates Kent Co. Mon. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the ¼ lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:			-				ection of
B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the ½ lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N							
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (ICRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the 1/2 lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. ICRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N	'		**				4
J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the ½ lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N		1004	San vey 10001ab	,			
J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the ½ lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N			•				
J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the ½ lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N							
J-6 Found standard Kent Co. Monument. Remaining witnesses check with those recorded in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the ½ lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:					Johlishina novnov		
in 1978 (LCRC #1174) by John A. Merdzinski. This monument is 0.2' South and 0.8' West of the intersection of the 1/4 lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak \$10°W 10.78' 16" Oak \$45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	В.					13	
0.8' West of the intersection of the \(\frac{1}{4} \) lines. The Kent County Remonumentation Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		J-6 Found standa	ird Kent Co. Monumer	it. Remaining witnes	sses check with	those records	ea.
Peer Group approved the monument as the center of section. LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	٠. `	in 1978 (LCR	C #1174) by John A.	. Merdzinski. Inis m	Wort County Por	onumentation	
LCRC #1174 14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:						Ondivendence	
14" Maple N85°E 16.73 16" Oak S10°W 10.78' 16" Oak S45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		- · ·	ipproved the monumen	it as the center of t	30002011		•
16" Oak \$10°W 10.78' 16" Oak \$45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		LCRC #1174					
16" Oak \$10°W 10.78' 16" Oak \$45°W 33.15' 4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		14". Maple	N85°E 16.73				
4" Basswood N15°W 27.05' Corner fence post (fence E/W/S) 7.0'W & 1.5'N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	37.		S10°W 10.78'		•		•
Corner fence post (fence E/W/S) 7.0 W & 1.5 N C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:			The second secon				
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		a ei			-		
[4] [1] [1] [1] [1] [1] [1] [1] [1] [1] [1		Corner fence	e post (fence E/W/S) /.U'W & 1.5'N			
[4] [1] [1] [1] [1] [1] [1] [1] [1] [1] [1						•	1 day 1 - 1
[4] [1] [1] [1] [1] [1] [1] [1] [1] [1] [1							
[4] [1] [1] [1] [1] [1] [1] [1] [1] [1] [1	C.	Description of monument	for corner and accessorie	s established to perpetuate	locating the position o	f the corner:	
						•	

Glaza & Associates, Inc.
Surveyor's Michigan License No.

K.C. remon tag & nail in S side 18" Maple K.C. remon tag & nail in E side 16" Oak

K.C. remon tag & nail in SE side 18" Oak Set K.C. remon tag & nail in E side 10" Basswood Set K.C. remon tag & nail in W side 12" Elm

> GLAZA ROFESSIONAL SURVEYOR

P.A. 345 1990 KENT COUNTY

16.73'

33.15'

26.92'

35.84'

1994 December 12,

N85°E

S45°W

N15°w

North

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983