REMONUMENTATION

APR 2 8 1995

STATE OF MICHIGAN COUNTY OF KENT REČĔIVĖD FÖR RECORD

	7.3	17774	30 B	
40 A	s is a		A 1 4	PA DAD
7 7	มาก	\mathbf{n}_{I}		าห

LAND CORNER RECORDATION CERTIFICATE LAND 9: 24 Filing Requirement of Act 74 Mich PA 1970

For corners in		ounty Remonumentatio	n on i
Kent (County)	Located In:	Corner Code ##	REG. OF DEEDS
Public Land Survey	T <u>7N</u> R <u>11W</u> T R	K-4 (E ½ cor, Sec 11)	, , , , , , , , , , , , , , , , , , ,
2. Property Controlling in Section	\$ T R \$ T R		7872
3. Miscellaneous Property in Sec.	S T R S T R	7	Register of Deeds Stamp & File Number

Recorded Plat 5. Private Claims

November James C. Glaza in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

K-4 1831	G.L.O.	Mullett	set post
1956	Kent Co. Wit.		stone & iron
1975	LCRC #867	Nederveld	"T" iron
1982	LCRC #2781	Merdzinski	set Kent Co. Mon.
1991	LCRC #6394	Marschall	Kent Co. Mon.

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by John A. Merdzinski on March 4, 1982 and was recorded per LCRC #2781.

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Found standard Kent Co. Mon. (Harrison) per witnesses from LCRC #2781 as set by John A. Merdzinski in place of a "T" iron he found and per witnesses from LCRC #6394.

LCRC #6394

Nail & tag in S side 16" Walnut	East	12.75'
Nail & tag in W side 12" Oak	S15°E	13.79'
Nail & tag in E side 10" Ash	s30°W	11.86'
Nail & tag in E side 16" Tri. Walnut	S01°E	30.71'
Nail & tag in W side 14" Ash	N15°E	13.82'
Nail & tag in SW side 12" Oak	N55°E	1.16'
C/L blacktop road (Maguire Ave.) is more or less 41'	West of	corner.

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Standard Kent County Monument

Nail & K.C. rem	on tag in S side	18" Walnut	East	12.75'
Set Nail & K.C. rem	on tag in W side	12" Oak	S15°E	13.77'
Set Nail & K.C. rem			s30°W	11.86'
Set Nail & K.C. rem	on tag in E side	18" Tri. Walnut	S01°E	30.70'
Set Nail & K.C. rem	on tag in W side	16" Ash	N15°E	13.82'
Set Nail & K.C. rem	on tag in NW side	12" Oak	N55°E	1.75
		is more or less 41'	West of	corner.

PEER APPROVED 10

1994 CHAIRMAN

Surveyor's Michigan License No. iates,

40166

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYO REVISED MAY 14, 1975

JAMES C **GLAZA** ROFESSIONA SURVEYOR No. 40166