SURVEY & REMONUMENTATION



	REMONUMENTA	TION .			3 3		
۰.	• • • • • • • • • • • • • • • • • • • •				STATE OF MICH	QAN	
\$7.00	APR 2 8 1995				COUNTY OF KE RECEIVED FOR RE	CORO	
\$2.00		B. B.					
	COMMISSIO	N LAND COR	NER RECORDATION	CERTIFICA	ME DEC 16 AM	9: 24	
For corners	보다 되는 사람들의 사람들이 되었다.	Filing Requ	irement of Act 74, I County Remonument	lich. P.A. 19	70		
			- · · · · · · · · · · · · · · · · · · ·	` .	Lind	lomal	
	County)	ocated in:	Corner Code =	#		$\sum_{i=1}^{n}$	
. 1 Dubbala	and Comment	- 7N - 11W	L-7 (S ½ co	_	REG. OF DE	FD2	-
I. Public La		T_ <u>7N_R_11W</u> TR	Sec 1				
i.		T R		=			
	1	TR					
2. Property		T R		 .	PJ Q	82	
in Section 3. Miscellar		TR T R		·			
		T R			Register of Deeds	Stamp & File Nu	ımber
		7			ί,		
	, Recorded Pla	at		-	- ABCD	EFGHI	JKL
5. Private C	laims	1.4			— "TŢŢŢ	TITI	TI
					3 5	1-1-3-1-	-2-1-1
		: 1					
, James	C. Glaza , in a field s	urvey on	November 25	19	5	1 1 1	11-12
do hereby cert	ify that under requirements of I	P.A. 74, Michigan P	A. of 1970, the corner poir	its mentioned	61817	16 15	14 13
ิเก lines ⊺ and current manua	2 above were in conformance of survey instructions of the	e with regulations United States Den	and rules therefore as re artment of the loterior. Bu	quired in the ureau of Land	7		
Management o	r by a decree of a Court of Law	and/or that the cor	ner points mentioned in li	nes 3, 4 and 5	8 19 20	21 22	23 24
	conformance with the rules of established, re-established				9		1 1 1
expressed bel		, mondinented, A	-monumented, jecoveje	su, louid as	10 30 29	26 27	2625
NOTE: Not	more than 4 corners, all ir	n the same town	and range, may be re-	corded	11		
on ti	nis certificate.	:			12 31-32-	33 - 34	3536
A Department	an affarial manner and a				13		
	on of original monument a 831 G.L.O		•	toration;			
		Co. Wit.	Mullett		set post iron pipe		
	1978 LCRC		Merdzinski		iron pipe		
	982 LCRC		Merdzinski		set Kent C	o. Mon.	
1	.987 W & W	,			Kent Co. M		
	.990 LCRC		Bueche		set Kent C	o. Mon.	
	991 LCRC		Marschall		Kent Co. M	on.	
'] T	The position of thi	s corner was	previously appr	roved by t	he Kent Count	y Remonumen	tation
	eer Group, monumen CRC #2787.	rea by your	A. Merdzinski o	1 March 5,	1982 and was	recoraea p	er
B. Description	on of corner evidence foun	nd and/or method	applied in restoring of	r reestablishi	ng corner:		
L-7 I	ound Kent Co. Mon.	(Harrison)	per witnesses fi	com LCRC #	5709 as set b	у	
J	ohn C. Bueche and	per witnesse	s from LCRC #640	05. The c	ounty mon. se	et .	
E	er LCRC #2787 was	destroyed du	e to road consti	ruction.			
·	CRC #6405				-		
7	ron			S45°E	100.01'		
7 NO.	ail & tag in North	side 10" Ce	dar	540°W	124.12'		
	ail & tag in S'ly			N65°E	100.52		
	Mail & tag in West			N25°E	91.27'		
(1) C	n C/L blacktop E-W	& South				•	
Taring day	lbo gollostod las''		Salara da Salara Anglas da Salara da	· · · · · · · · · · · · · · · · · · ·			
	he selected location in the book of the bo	on is accept The lieus tea	eu by me and is	generally	accepted by	proressional	T
	on of monument for corner						•
•			adiaphoned to perper	iveating	are position of the	, 50mgr.	
L-7 S	tandard Kent County	y Monument		•			
Т	ron			S45°E	100.01'		
	ail & tag in S'ly	side 1' dia	. fence post	N65°E	100.01		
	ail & tag in West			N25°E	91.27'	TEOF	MICHI

Date Z

S55°W

P.A. 345 1990 KENT COUNTY

98.651

JAMES C GLAZA PROFESSIONAL SURVEYOR No. 40166

Giaza & Associates, Surveyor's Michigan License No. 40166

Set Nail & tag in North side Triple Cedar

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197 REVISED JAN., 198