
SURVEY & REMONUMENTATION





APR 28 1995

LAND CORNER RECORDATION CERTIFICATE PACIFICATION

For	comers in	Filing	Require	ment of Act 74, M JNTY REMONUME	ich. P.A. 1970 NTATION							•	
	Kent	Located in:		Corner Code #				2	Efr.	7			٠.
	(County)	Located in:	İ	Contact Code #	į.		Ú.	~~<	Z.	~~\			
1.	Public Land Survey	T <u>_7N</u> R T R T R		1-11	-		REG	. OF (DEEO!	5			
	Property Controlling in Section	STR STR					\	78	35				
3.	Miscellaneous	S T R			ľ	1-4-	£ F	laada (C+a	& File	Manage	. معسما	
	Property in Sec.	S T R				egiste	01 1	/eeus	Stamp	α riie	MUMI	Jei	·
4.	Lot No,	Recorded Plat					_					, <u>.</u>	
5.	Private Claims					Â		C D	E F	G H	- - 	K	L · 1
						2	è	 		_	-	} - }-	-}-
		•				3 -	_	-	1				
l	Randy Kolehouse	, in a field survey on _	July 6	5	19 94 .	4 -		 	- <u> </u>	_ 0	_ _,	1	 -12
curre Mana abov Cour	ent manual of survey inst agement or by a decree o e were in conformance w	in conformance with regular tructions of the United State of a Court of Law and/or that with the rules of the Michigan of, re-established, monume	es Departn the corner n Board of I	nent of the interior, I points mentioned in I Land Surveyors or by	Bureau of Land ines 3, 4 and 5 a Decree of a	6 7 8 9	-19	20-	21-	22		3-	-24
NOT	E: Not more than 4	corners, all in the same t	town and i	range, may be reco	rded	10	—30]	29-		27-		;	-25-—
•	on this certificate	e. :	:			11 -					1		9
A.	Description of origin	al monument and acces	sories an	d/or subsequent re	storation:	13]						
L-11		O. Notes	Mullett		Set Post								
		R.C. #180	Williams 8		Conc. Mon.								
		R.C. #1474	Williams 8		Fnd. Conc. Mo		K.C	Mon.					
	1991 L.C.	R.C. #6407	Marschall		K.C. Monumen	t.							
		inally approved by the K nd was recorded per L.C.			n Peer Group a	nd mo	onum	nented	by W	'illiams	. &		
В.	Description of corne	er evidence found and/or	method	applied in restoring	or reestablishi	ng coi	ner:	:					
L-11		t County Monument 300'. C.R.C.'s #1474 and #640'											
	L.C.R.C	C. #1474	Ì		L.C.R.C. #6	407							
	NW cor. garage fram NE cor. garage frame Iron in concrete W 83 SE cor. hse. fndn. N	3 S 30° W 75.27' 3° W 19.81'		NE cor. Iron in c	garage frame S garage frame S oncrete W 83° V hse, fndn, N 62°	30° W V 19.8	/ 75.: 11'				÷		•

SE cor. hse. fndn. N 62° W 59.20' SE cor. coric. porch - floor N 70° E 66.70' K.C. nail & tag SW side 40" Oak N 40° W 2.53' Corner is more or less 300' W of C/L Carhoustie Ave. On E-W tree line and tree line to the North

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original co

	or the position of the original corner.	
) .	Description of monument for corner and accessories	established to perpetuate locating the position of the corner:

11	Standard Kent County Monument				
	NW cor. garage frame S 3° W 36.74'				
	NE cor. garage frame S 30° W 75.28'	P.A. 3			
	Iron in concrete W 83° W 19.81'	PEER			
	SE cor. hse. fndn. N 62° W 59,20'	CHAIR			
	SE cor. conc. porch - floor N 70° E 66.70°				
	Nail & K.C. remon. tag SW side 40" Oak N 40°	W 2.53			

SE cor. conc. porch - floor N 70° E 66.70'

P.A. 345 1990 KENT COUNT PEER APPROYED /// CHAIRMAN

KOLEHOUSE LAND SURVEYOR No.

Corner is more or less 300' W of C/L Carhoustie Ave. On E-W-tree line and tree line to the North

Date

≡igned by ≣urveyor's Michigan License No.