



STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

APR 2 8 1995

COMMISSION LAND CORNER RECORDATION CERTIFICATE Filling Requirement of Act 74, Mich. P.A. 1970

94 DEC -6 AH 9: 06

For comers in	J	KENT COUNTY REI	MONUMENTATION	
Kent (County)	Located in:	Corner	Code #	Lingford
1. Public Land Surve	T R T R			REG. OF DEEDS
 Property Controlling in Section Miscellaneous Property in Sec. 	T R S T R S T R S T R			7840 Register of Deeds Stamp & File Number
I, Randy Kolehouse do hereby certify that unin lines 1 and 2 above current manual of survey Management or by a decabove were in conformar	, in a field survey on _ der requirements of P.A. 74 Mich were in conformance with regu y instructions of the United Stat ree of a Court of Law and/or that nce with the rules of the Michigal ished, re-established, monume	higan P.A. of 1970, the lations and rules the test Department of the title corner points me in Board of Land Survey.	e corner points mentione prefore as required in the interior, Bureau of Lan ntioned in lines 3, 4 and eyors or by a Decree of	ad a 19 20 21 22 23 24 35 9
NOTE: Not more the on this certification	nn 4 corners, all in the same licate.	town and range, ma	ly be recorded	10 30 23 28 27 28 25 11 2 31 32 33 34 35 38
A. Description of o	riginal monument and acces	ssories and/or subs	equent restoration:	13
M-11 1831 G.I	O. Notes	L. Lyon	Set Post	P.A. 345 1990 KENT COUNTY PEER APPROVED //////// CHAIDMAN Frangleuter

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Maurice J. Rosema on 6/25/84 and was recorded per L.C.R.C. #3869. This corner is common with A-11 T7N R10W.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M-11 Found standard Kent County Monument per L.C.R.C.'s #3869 and #6414 as set by M. Rosema in place of a 3/4" iron at a fence corner N-S & W he found which checked L.C.R.C. #3269.

L.C.R.C. #3869

L.C.R.C. #6414

Nail &. remon. tag in NE side dbl. 18" Oak N 52° W 27.58'

Nail & tag NE side twin 22" Oak N 50° W 27.64'
Nail & tag W side twin 22" Oak N 25° W 33.33'
Nail & tag S side 40" Mapte N 89° W 34.29'
Nail & tag N side 6" Ash N 90° W 4.75'
Nail & tag W side 10" Oak S 15° E 21.11'
Corner is at remains of fence N-W and to West

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original comer.

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Nail & K.C. remon. tag NE side twin 22" Oak N 50° W 27.64'

Nail & K.C. remon. tag W side twin 22" Oak N 25° W 33.33'

Nail & K.C. remon. tag S side 40" Maple N 89" W 34.29"

Nail & K.C. remon. tag N side 6" Ash N 90° W 4.75"

Nail & K.C. remon. tag W side 10" Oak S 15 E 21.11"

Corner is at remains of fence N-W and to West

RANDY J.

KOLEHOUSE
LAND
SURVEYOR

No.
25854

C LAND SURVEYOR

igned by Karly Hollissesses

-urveyor's Michigan License No. 25854

M APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1933