



RECEIVED FOR RECORD

94 DEC -6 AM S: 06

APR 2 8 1995

For comers in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 KENT COUNTY REMONUMENTATION

Lind Sand
REG. OF DEEDS

Kent (County) Corner Code # Located in: **Public Land Survey** T_7N__ R 11W M-12 R R R **Property Controlling** in Section R Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

, Recorded Plat 5. Private Claims

Randy Kolehouse in a field survey on do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a established, re-established, monumented, re-monumented, recovered, found as Court of Law: expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

M-12 1831 G.L.O. Notes .. Lyon Set Post 1953 K.C. Surveyor Wit. Map 1977 L.C.R.C. #1386 Nederveld 3/4" Iron 1979 L.C.R.C. #1622 All Points 3/4" Iron 1984 L.C.R.C. #3870 Rosema Set K.C. Mon. 1991 L.C.R.C. #6416 Marschall K.C. Monument

1" Iron in Mon. Box P.A. 345 1990 KENT COUNT PEER APPROVED _///3

This comer was originally approved by the Kent County Remonumentation Peer Group and monumented by Maurice J. Rosema on 6/21/84 and was recorded per L.C.R.C. #3870.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-12 Found standard Kent County Monument at the C/L intersection of Ada Drive running E-W and Patterson Avenue running South per L.C.R.C.'s #3870 and #6416 as set by M. Rosema by reconstructing plats in area. (Note L.C.R.C.'s #1386 and #1622 corner is 1.39' North and 0.8' West of this point.) Point established checked K.C. surveyor's records.

L.C.R.C. #3870

L.C.R.C. #6416

Nail and remon. tag in E side 30" Maple N 69° W 65.10" Nail and remon. tag in S side 30" Maple N 72° E 75.13'

Nail & tag S side 26" Maple N 70° W 65.00' Nail & tag NE side 12" Maple S 57° W 70.75" SE cor. conc. pump station more or less 10x15 S 30° W 69.55' Top C/L nut fire hyd. N 35° € 31.91' Nail & tag SE side 36" Maple N 71° E 75.09'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original comer.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-12 Standard Kent County Monument

Nail & K.C. remon. tag S side 26" Maple N 70° W 65.00' Nail & K.C. remon. tag NE side 12" Maple S 57° W 70.75' SE cor. 10x15 conc. pump station S 30° W 69.55' Top C/L nut fire hyd. N 35° E 31.91' Nail & K.C. remon. tag SE side 36" Maple N 71° E 75.09'

Date

RANDY J. KOLEHOUSE SURVEYOR 25854 CO LAND SUP

Surveyor's Michigan License No.