

For corners in

REMONUMENTATIO

APR 2 8 1995

KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN REČĚÍVED FÖR RĚCORD

LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

94 NOV 28 AM 11: 42

| KENT COUNTY | Located In: | Corner Code =## | Level from to |
|--|-----------------------------------|---|--|
| Public Land Survey | T R T R T R T R | A-5 | REG. OF DEEDS |
| Property Controlling in Section Miscellaneous Property in Sec. | S T R S T R S T R S T R | | 7272 Register of Deeds Stamp & File Number |
| | Recorded Plat | | 2 6 5 4 3 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 |
| do hereby certify that under red in lines 1 and 2 above were in current manual of survey instr Management or by a decree of above were in conformance wi | in a field survey on | 1970, the corner points mentioned rules therefore as required in the lent of the Interior, Bureau of Landpoints mentioned in lines 3, 4 and 5 Land Surveyors or by a Decree of a line of the land Surveyors or by a Decree of | 1 6 18 17 16 15 14 13 15 15 15 15 15 15 15 15 15 15 15 15 15 |
| NOTE: Not more than 4 c | corners, all in the same town and | range, may be recorded | 11 |

A. Description of original monument and accessories and/or subsequent restoration:

| A-5 | 1836 | GLO | | Brookfield | Set Post (common with M-5, T7N, R13W) |
|-----|------|--------------|-----|------------|---------------------------------------|
| | 1949 | Kent Co. Wit | | | 3" Iron |
| | 1975 | LCRC #828 | 1 | Chambers | 3" Iron |
| | 1977 | LCRC #970 | | McCloskey | -t" Iron |
| | 1980 | LCRC #1329 | | By1 | 3" Iron Pipe |
| | 1981 | LCRC #1847 | | Shangraw | Set Kent County Monument |
| | 1990 | LCRC #5499 | - 1 | Starr | Kent County Monument |
| | | | | | |

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Carl F. Shangraw on 5/20/81 and was recorded per LCRC #1847.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-5 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Carl F. Sahngraw in place of the 3" Iron and mon. box he found. Said 3" Iron in mon. box checks with Kent Co. Wit. and LCRC's #828 & #970 & #1329.

| <u>LCRC #1847</u> | | LCRC #5499 |
|-------------------------|-------------|--------------------------------------|
| KC Nail & tag P. Pole | S50°E 32.20 | ' Nail & KC tag P. Pole S45°E 37.89' |
| KC Nail & tag 36" Maple | N30°W 59.54 | ' Nail & KC tag P. Pole N40°W 36.92' |
| KC Nail & tag P. Pole | N50°E 36.92 | ' Nail & KC tag P. Pole S50°W 63.25' |
| KC Nail & tag Fc. Post | S45°W 45.70 | ' Nail & KC tag P. Pole N50°E 41.20' |
| 3/4" Iron | East 4.95 | ' 3/4" Iron East 4.95' |
| | | On C/L E-W Rit Rd . On C/L N-S Cray |

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

| С. | Description of monument for corner ar | nd accessories established to per | rpetuate locating the positi | on of the corner: |
|-----|---------------------------------------|-----------------------------------|------------------------------|--|
| | A-5 Standard Kent County M | Monument | | The state of the s |
| | Nail & KC Remon. t | tag SW side P. Pole | S45°E 37.89' | |
| | | <u> </u> | N40°W 36.98' | |
| | Set Nail & KC Remon. t | _ | S50°W 63.41' | William R. V. |
| | Set Nail & KC Remon. t | _ | N70°E 108.59' | Registered Land |
| | 3/4" Iron | | East 4.95' | Surveyor Jan |
| | On C/L E-W BIT. Rd.; C | on C/L Grav. Rd. S.; On | | No. |
| | | P.A. 845 1990 KEN | 11/17/QC | 23502 |
| | | PEER APPROVED | | |
| | | CHAIRMAN AZ | ery Huhe | 21 |
| | 1/ 1/ 1/ | | 111120 | 7. |
| Sia | ned by | | Date | <u> </u> |
| _ | · | 1 22807 | , , | • |
| _ | vevor's Michigan License No. | 12807 | • (| • |